

## GOVERNMENT OF SINDH CULTURE, TOURISM & ANTIQUITIES DEPARTMENT

## **NOTIFICATION**

No. OSD/CHC/RYQ-01-49/2017: In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

### (RAILWAY QUARTERS KARACHI)

S.NO.	NAME OF BUILDING	PLOT #	ADDRESS	REASON FOR ENLISTMENT AS HERITAGE
1.	Hussiani Manzi!	RY-4/ 13,	Talpur Road (Wood Street);	Architectural Value
2.	Finlay House	RY-5/ 3/ 1,	I. I. Chundrigar (McLeod) Road;	Architectural Value
3.	Khairabad	RY-9/ 11/ 1,	I. I. Chundrigar (Mcleod) Road. Dr. Ziauddin Ahmed (Kutchery)	Architectural Value
4.	Dawood Corporation (PIA) Ltd (Messers Ralli Brothers)	RY-15/ 1,	Talpur Road (Wood Street), Leckil Road;	Architectural Value
5.	KPT Warehouses (Clements Robson & Co.)	RY-15/ 2,	Talpur Road (Wood Street), Leckil Road;	Architectural Value
6.	KPT Warehouses	RY-15/3,	otT Talpur Road (Wood Street). Leckil Road;	Architectural Value
7.	KPT Warehouses (Messers Ralli Brothers)	RY-15/ 4,	Talpur Road (Wood Street). Leckil Road;	Architectural Value
8.	Khan Mansion	RY-4/ 12,	I. I Chundrigar (McLeod) Road. Talpur Road (Wood Street);	Architectural Value
9.	Ocean Centre (Vulcan Iron Work)	RY-I5/ 5,	Mc. Hinch Road, Talpur Road (Wood Street);	Architectural Value

10.	Mehersons Estate (Waqaf Muhammad	RY-16/ 1,	Talpur Road (Wood Street), Leckil Road;	Architectural Value
11.	Meher Elahi) KPT Warehouses	RY-17/ 1,	Talpur Road ( Wood Street), Leckil Road;	Architectural Value
12.	KPT Warehouses	RY-17/ 2,	Queens Road, Leckil Road;	Architectural Value
13.	KPT Warehouses	RY-17/3,	Mumtaz Hussain (Dunally) Road, Queens Road;	Architectural Value
14.	Bank Alfalah (BCCI Building)	RY-4/ 3, 4,	I. I. Chundrigar (McLeod) Road, Mumtaz Russian (Dunally) Road	Architectural Value
15.	Water Trough (Kemari Jetty Flyover)		M. A. Jinnah (Bunder) Road, I. I Chundrigar (McLeod) Road	Architectural Value
16.	Railway Shed/ Railway Police Chowki	Railway Shed/ RY-1/ 1, M. A. Jinnah (Bunder Rilway Police I. Chundrigar (McLe		Architectural Value
17.	Steel Structure/ Railway Shed/	RY-1/ 1,	M. A. Jinnah (Bunder) Road, I. I. Chundrigar (McLeod) Road	Architectural Value
18.	Emirates Bank International Ltd. (Lloyd's Bank) (Silk Bank)	RY-1/2,	I. I. Chundrigar (McLeod) Road, Kattyan Road, Karachi	Architectural Value
19.	State Bank of Pakistan Annexe (Bank of India)	RY-4/ 2, I. I.	Chundrigar (McLeod) Road, Mumtaz Hassian (Dunally) Road, Karachi	Architectural Value
20.	Badri Building	RY-4/ 10, 11,	I. I. Chundrigar (McLeod) Road, Karachi	Architectural Value
21.	Messer's Rally Brothers Building	RY-4/ 15,	Talpur Road (Wood Street), off I. I. Chundrigar (McLeod) Road, Karachi	Architectural Value
22.	Beaufort Building (P & O Plaza)	RY-5/ 3/ 2, 4/ 1, 4/ 2,	I. I. Chundrigar (McLeod) Road, Karachi	Architectural Value
23.	Grindlays Bank Building	RY-5/ 5,	I. I. Chundrigar (McLeod) Road, Wallace Road, Karachi	Architectural Value
24.	Eastern Express Company Building	RY-5/ 5,	I. I. Chundrigar (McLeod) Road, Wallace Road, Karachi	Architectural Value
25.	City Station Building	RY-3/1,	I. I. Chundrigar (McLeod) Road, Wallace Road, Karachi	Architectural Value

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

Secretary to Govt. of Sindh Karachi dated the 23<sup>rd</sup> January,

No.OSD/CHC/RYQ-01-49/2017 2018

#### A copy is forwarded for information and necessary action to:-

- 1. The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
- 2. The Chairman, Planning & Development Board, Govt. of Sindh.
- 3. The Chairman, Technical Committee on Sindh Cultural Heritage.
- 4. The Administrative Secretaries (All), Government of Sindh.
- 5. The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
- 6. The Commissioner, Karachi.
- 7. The Director General, Sindh Building Control Authority.
- 8. The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
- 9. The Director (Heritage), CT&AD, Government of Sindh
- 10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
- 11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
- 12. The Chief Executive Officer, Cantonment Board, Karachi.
- 13. The Deputy Commissioner-South, Karachi.
- 14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
- PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
- 16. The Owner / Occupant.
- 17. Notification File.

SECTION OFFICER (HERITAGE)

For Secretary to Govt. of Sindh

#### KARACHI HERITAGE BUILDINGS

## **RE-SURVEY PROJECT**


## CONDUCTED BY: CULTURE, TOURISM & ANTIQUITIES DEPARTMENT



RAILWAY QUARTER KARACHI DECEMBER 2017


## **WATER TROUGH**

1	IDENTIFICATION:	1922



## EMIRATES BANK INTERNATIONAL L.TD (LLOYDS BANK)


	1.	IDENTIFICATION:	G+3 1932
--	----	-----------------	----------



1							
11.	COMMENTS:	Addition & Alteration on top but well maintained.					
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its historic and architectural value.					
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh					
14.	DATE:	13.11.2017					


## KARACHI BUNDAR RAILWAY POLICE CHOWKI

1.	IDENTIFICATION: Site Name:	KARACHI BUNDAR RAILWAY POLICE CHOWKI	
	Other Names:		
2.	LOCATION:		



#### RAILWAY SHED

1.	IDENTIFICATION:	
	Site Name:	RAILWAY SHED
	Other Names:	
2.	LOCATION:	
	Address:	Opposite E.F.U house, Near Tower,
		Netty Jetty Pul, M.A Jinnah
		Road(Bunadar) road/ I.I Chandigarh
		Road ( Mec Lead) Road



#### STATE BANK OF PAKISTAN ANNEXE


1.	IDENTIFICATION:		
	Site Name:	STATE BANK OF PAKISTAN ANNEXE	
		BUILDING( BANK OF INDIA)	



	Other Names:	State Bank Museum			
2.	LOCATION:				
	Address:	Beside State Bank, I.I Road	Chandigarh		
	Survey No.	Plot No.	Sheet No.		
	Coordinates	N-24°50.927	E-66°59.968		
	District/City/ Town/ Karachi	/ Village: : Railway Quarter's South			
3.	OWNERSHIP:	Private	Government √		
	Name of Owner (s) Government of Pakistan		Government		

4.	OCCUPANCY:	Museum Of State Bank							
5.	REASONS FOR PROTECTION:	Architectural	Value: C	Columns, C	ornices,	Portal,	Courtyard,		
		Decorative Pa	rapet & Lio	n Head on P	arapet				
6.	MEASUREMENT:	Height- 35'	Height- 35' Length- 126' Width-10						
7.	CONSTRUCTION MATERIAL:	Stone Masonr	Stone Masonry, Charoli						
8	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Co	ndition	٧ N	leeds repair		
9.	THEREAT(S):	No.							

10. LOCATION MAP PHOTOGRAPHS:








11.	COMMENTS:	Well Maintained but interior has been renovated.
12.	RECOMMENDATIONS	Deserves to be declared as protected heritage due to historical and architectural value.
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh
14.	DATE:	13.11.2017

## **BADRI BUILDING**

1.	IDENTIFICATION:	1901	G+1
	Site Name:	BADRI BUILDING	
	Other Names:		
2.	LOCATION:		



		· · · · · · · · · · · · · · · · · · ·
11.	COMMENTS:	Partially renovated, but seems to be in stable condition.
12.	RECOMMENDATIONS	Deserves to be declared as protected heritage due to its historical & architectural value.
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh
14.	DATE:	16-11-2017


#### **MESSER'S RALLY BROTHERS BUILDING**

	1.	IDENTIFICATION:	1920 G+1	
		Site Name:	MESSER'S RALLY BROTHERS	
NO PERMISSION			BUILDING	
		Other Names:		

		2.	LOCATION:		
			Address:	Talpur Road(Wood	
			Survey No.	Plot No.4/15	Sheet No.
			Coordinates	N-24°50.864	E-67°00.144
			District/City/ Towr Karachi	n/ Village: : Railway C	Quarter's South
		3.	OWNERSHIP:	Private	Government √
			Name of Owner (s)		GOVERNMENT
			Provincial		
			Government		
4.	OCCUPANCY:	Co	mmercial		
5.	REASONS FOR PROTECTION:	Arch	nitectural Value:		
6.	MEASUREMENT:	Heig	ght- Len	gth- Wid	th-
7.	CONSTRUCTION MATERIAL:				
8.	STATUS / PRESENT CONDITION	Dila	pidated Stable v	Good Condition	Needs repair
9.	THEREAT(S):				
10.	LOCATION MAP	PHOTOGRAPHS:			
	Location Map				
11. 12.	COMMENTS: RECOMMENDATIONS		structure is in stak	ole condition.	declared as
		pro	•	ge due to its	
13.	NAME OF INVESTIGATOR:	Abd	lul Fatah Shaikh		
14.	DATE:		1-2017		

## BEAUFORT BUILDING (P & O PLAZA)

1.	IDENTIFICATION:		1924
	Site Name:	BEAUFORT BUILDING	G (P & O PLAZA)
	Other Names:		
2.	LOCATION:		
	Address:	I.I Chandigarh road	
	Survey No.	Plot No.5/3/2	Sheet No.



# GRINDLAYS BANK BUILDING (STANDARD CHARTERED BANK)

	1.	IDENTIFICATION:	1921
NO PERMISSION		Site Name:	GRINDLAYS BANK BUILDING
		Other Names:	

		2.	LOCATI	ON:		
			Addres	s:	I.I Chandigarh (McLeod) Road Wallace Road	
					Plot No.5/5	Sheet No.
			Coordin	nates	N-24°50.947	E-67°00.328
			District Karachi	-	Village: : Railway C	Quarter's South
		3.	OWNER	SHIP:	Private	Government
			Name o UNKNO	f Owner (s) WN		
4.	OCCUPANCY:		Comme	rcial	1	
5.	REASONS FOR PROTECTION:	Arch	itectural	Value:		
6.	MEASUREMENT:	Heig	ht-	Length	- Width	)-
7.	CONSTRUCTION MATERIAL:					
8	STATUS / PRESENT CONDITION	Dila	oidated	Stable	Good Condition	√ Needs repair
9.	THEREAT(S):					
10.	Location Map	РНО	TOGRAP	пъ:		
11.	COMMENTS:	Buil	ding is w	vell maintair	ned.	
12.	RECOMMENDATIONS	Des	serves	to be dec		ected heritage al value.
		uuc			in al cittoccul	ai raiuui
13.	NAME OF INVESTIGATOR:	Ahd	ul Fatah			

## **EASTERN EXPRESS COMPANY BUILDING**


1.	IDENTIFICATION:	
	Site Name:	EASTERN EXPRESS COMPANY
		BUILDING
	Other Names:	
2.	LOCATION:	
	Address:	I.I Chandigarh Road, (McLeod) Road,
		Wallace Road Behind City Station.



	Survey No.	Plot No.5/5	Sheet No.
	Coordinates	N-24°00.930	E-67°00.337
	District/City/ Town/	Village: : Railway Qua	rter's South
	Karachi		
3.	OWNERSHIP:	Private √	Government
	Name of Owner (s) UNKNOWN	PRIVATE	

4.	OCCUPANCY:	Commercial but store of standard charted Bank						
5.	REASONS FOR PROTECTION:	Architectural Value: Arched window, Rosettes, Courty	Architectural Value: Arched window, Rosettes, Courtyard, Pitched					
		roof, Embossed stone masonry						
6.	MEASUREMENT:	Height- Length- Width-						
7.	CONSTRUCTION MATERIAL:	Stone masonry,						
8	STATUS / PRESENT CONDITION	Dilapidated Stable Good Condition V	Needs repair					
9.	THEREAT(S):	Encroachment	Encroachment					
10	LOCATION MAD:	DHOTOGRADHS.	DUOTOGRADUS:					

10. | LOCATION MAP:








11.	COMMENTS:	Partially maintained and seems to be in good condition.
12.	RECOMMENDATIONS	Building deserves to be declared as protected heritage due to its historical and architectural value.
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh
14.	DATE:	21-11-2017


## **CITY STATION BUILDING**

1.	IDENTIFICATION:	:	1939
	Site Name:	CITY STATION BUILD	ING
	Other Names:		
2.	LOCATION:		
	Address:	I.I Chandigarh Road (	McLeod) Road,
		Wallace Road.	
	Survey No.	Plot No.3/1	Sheet No.



#### **KHAN MANSION**

1.	IDENTIFICATION:	1920
	Site Name:	KHAN MANSION
	Other Names:	



	1.07	
11.	COMMENTS:	Only outer walls are left which are stable but rest of the
		building has demolished.
12.	RECOMMENDATIONS	Deserves to be declared as protected heritage
		due to social and architectural value.
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh
14.	DATE:	16-11-2017

NOTE: The private Pathan chokidar has misbehaved with the team and did not take gave any information except owner's name.

Location Map

#### **HUSSIANI MANZIL**

IDENTIFICATION:	1920 G+1
Site Name:	HUSAINI MANZIL
Other Names:	United coffee House
LOCATION:	
	Site Name: Other Names:



4.	OCCUPANCY:	Commercial					
5.	REASONS FOR PROTECTION:	Architectural V	Architectural Value: Arch window, Cornices, Pilaster				
6.	MEASUREMENT:	Height- 20' Length-84' Width-53'				lth-53'	
7.	CONSTRUCTION MATERIAL:	Stone Masonry	Stone Masonry, Charoli				
8	STATUS / PRESENT CONDITION	Dilapidated Stable √ Good Condition Needs re			Needs repair		
9.	THEREAT(S):						
10.	LOCATION MAP:	PHOTOGRAPHS:					




Location Map



11.	COMMENTS:	The building has been renovated & coloured but Partially
		demolished.
12.	RECOMMENDATIONS	Building deserves to be declared as protected
		heritage due to its social and architectural value.
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh
14.	DATE:	16-11-2-17

## **FINLAY HOUSE**

IDENTIFICATION:	1928
Site Name:	FINLAY HOUSE
Other Names:	
LOCATION:	
Address:	I.I Chandigarh (McLeod) road
	Site Name: Other Names: LOCATION:



11.	COMMENTS:	Interior has been Renovated and well maintained.		
12.	RECOMMENDATIONS	Deserves to be declared as protected heritage		
		due to historical and architectural value.		
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh		
14.	DATE:	16-11-2017		

ROAD

LECKIL

Location Map

## **KHAIRABAD SHOP**

1.	IDENTIFICATION:	G+1
	Site Name:	KHAIRABAD SHOP
	Other Names:	




# DAWOOD CORPORATION (Pvt.) Ltd (Messer's Ralli Brothers)

1.	IDENTIFICATION:

NO PERMISSION			Site Name:	DAWOOD CORPORA MESSERS RALLI BRO	` , , `
			Other Names:		
		2.	LOCATION:		
			Address:	Talpur Road, (wood Road) Near City stat	
			Survey No.	Plot No.15/1	Sheet No.
			Coordinates	N-45°50.792	E-67°00.152
			District/City/ Town/	Village: Railway Quar	ter's South
•		3.	OWNERSHIP:	Private √	Government
			Name of Owner (s) UNKNOWN	PRIVATE	
4.	OCCUPANCY:				
5.	REASONS FOR PROTECTION:	1	nitectural Value: Only pidated condition	y walls & Courtyard	s are remain &
6.	MEASUREMENT:	_		h- 200' V	Vidth-180'
7.	CONSTRUCTION MATERIAL:	Stor	ne masonry, Charoli		
8	STATUS / PRESENT CONDITION		pidated V Stable	Good Condition	Needs repair
9.	THEREAT(S):		ition & Alteration on fr	ont side	
10.	LOCATION MAP:	PHO	TOGRAPHS:		
	LECKIL ROAD  OUEENS ROAD  MC HINCH ROAD  Location Map				
11.	COMMENTS:	port	st of the building l tion is in dilapidated	condition.	
12.	RECOMMENDATIONS	Bui	lding deserves to b	e declared as prot	ected heritage
12.	RECOMMENDATIONS		to its historical an	d architectural va	•
13.	NAME OF INVESTIGATOR:	due	0	d architectural va	•


## **KPT Warehouse (Clements Robson & Co.)**

1.	IDENTIFICATION:	
	Site Name:	KPT WAREHOUSE (CLEMMENTS
		ROBSON & CO.)
	Other Names:	
2.	LOCATION:	




### **KPT WAREHOUSES**

1.	IDENTIFICATION:	1920
	Site Name:	KPT WAREHOUSES
	Other Names:	




## **KPT WAREHOUSES (MESSERS RALLI BROTHER)**

1.	IDENTIFICATION:	1920
	Site Name:	KPT WAREHOUSES OMESSERS RALI
		BROTHERS)
	Other Names:	
2.	LOCATION:	



## OCEAN CENTRE (VULCAN IRON WORK)

1.	IDENTIFICATION:	G+1
	Site Name:	OCEAN CENTRE (VULCAN IRON
		WORK)
	Other Names:	
2.	LOCATION:	



# MEHERSONS ESTATE (WAQAF MUHAMMAD MEHAR ELAHI)

22-11-2017

Abdul Fatah Shaikh


13.

14.

DATE:

NAME OF INVESTIGATOR:

1.	IDENTIFICATION:	1900
	Site Name:	MEHARSONS ESTATE (WAQAF
		MUHAMMAD MEHAR ELAHI)
	Other Names:	




#### **KPT WAREHOUSE**

		IDENTIFICATION:	1920	
		Site Name:	KPT WAREHOUSE	
		Other Names:		
NO PERMISSION		LOCATION:		
		Address:	Behind Police Head	office, Mumtaz
			Husssain (Decendly	Road)
		Survey No.	Plot No.17/1	Sheet No.

			Coordinat	tes	N-24°50.816	E-66°59.978
			District/City/ Town/ Village: Railway Quarter's South			
		3.	3. OWNERSHIP:		Private √	Government
			Name of C	Owner (s)	PRIVATE	
			Sheikh Ab	id		
			Hussain			
4.	OCCUPANCY:		Comm			
5.	REASONS FOR PROTECTION:			alue: Arch volumes	•	s, Courtyard, Pitched
6.	MEASUREMENT:		ht-35'	Length		Width-40'
7.	CONSTRUCTION MATERIAL:		e masonry,			
8	STATUS / PRESENT CONDITION		oidated	Stable √	Good Condition	Needs repair
9.	THEREAT(S):	Addi	tion & Alte	ration		
10.	LOCATION MAP:	PHO	TOGRAPHS	<b>i:</b>		
	Location Map					
11.	COMMENTS:	Pitched roof has been demolished but the present Iron sheet roof is in stable condition.				
12.	RECOMMENDATIONS	Des	Deserves to be declared as protected heritage due to its historic and architectural value.			
13.	NAME OF INVESTIGATOR:	Abdul Fatah Shaikh				. MI PHINO!
14.	DATE:	21-11-2017				
	1		1 2017			


## **KPT WAREHOUSES**

1.	IDENTIFICATION:	G+1		
	Site Name:	KPT WAREHOUSES		
	Other Names:			
2.	LOCATION:			
	Address:	Behind Police Head office, Mumtaz		
		Husssain (Decendly Road)		
	Survey No.	Plot No.17/2	Sheet No.	
	Coordinates	N-24°50.800	E-66°59.984	
	District/City/ Town/	Village: Railway Quarter's South		
3.	OWNERSHIP:	Private	Government √	



#### **KPT WAREHOUSE**

1.	IDENTIFICATION:	G+1
	Site Name:	KPT WAREHOUSE
	Other Names:	Pir Bhi Warehouse & Ideal Trade Corporation



## BANK ALFALAH (BCCI BUILDING)

IDENTIFICATION:	G+1
Site Name:	BANK ALFALAH (BCCI BUILDING)
Other Names:	BANK ALFALAH BUILDING
LOCATION:	
	Other Names:

Retrieval to			Address	••	I.I Chandigarh road	
A			Survey No.		Plot No.4/3,4 N-24°50.936	Sheet No. E-67°00.002
#		Coordinates				E-67 00.002
		District/City/ Town/				T
		3.	OWNER		Private V	Government
			DUBAI 6	f Owner (s) Group	PRIVATE	
4.	OCCUPANCY:		Ban	k Alfalah		
5.	REASONS FOR PROTECTION:	Arch	itectural			
6.	MEASUREMENT:		ht- 70 '		h- 110′ \	Width-100'
7.	CONSTRUCTION MATERIAL:			<u>~</u>		
8	STATUS / PRESENT CONDITION	Dila	oidated	Stable	Good Condition √	Needs repair
9.	THEREAT(S):	Encr	oachmen	t Beside the I	Building	
10.	LOCATION MAP:	PHC	TOGRAPI	HS:		
	Location Map					ASSESSION OF THE PROPERTY OF T
11.	COMMENTS:				terior is covered w	
12.	RECOMMENDATIONS				lared as prote	
		due to historic and architectural value.				
13.	NAME OF INVESTIGATOR:	Abd	ul Fatah	Shaikh		
4.4	DATE	24.4	4 2047	•		-

21-11-2017

14.

DATE: