



9

48

GOVERNMENT OF SINDH
CULTURE, TOURISM &
ANTIQUITIES DEPARTMENT

NOTIFICATION

No. OSD/CHC/JAILQ-01-49/2017: In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(JAIL QUARTER KARACHI)

S.NO.	NAME OF BUILDING	PLOT #	ADDRESS	REASON FOR ENLISTMENT AS HERITAGE
1.	Nigar Cinema	WO-1/ 1,	Shahrah-e-Altif Hussain (Napier Road). Nishtar (Lawrence) Road;	Architectural Value
2.	Unknown	WO-1/ 23,	Mohammad Shah Street:	Architectural Value
3.	Tapal House	WO-1/ 24,	Wadhmal Oodharam (Nanakwara) Road, Mohammad Shah Street;	Architectural Value
4.	Nooruddin Norman Building Sultan Building	WO-1/ 32,	Shahrah-e-Altif Hussain (Napier Road). Gul Mohammad Street:	Architectural Value
5.	Halai Waqf Property	W-01/ 57,	Shahrah-e-Altif Hussain (Napier Road), Daryalal Street;	Architectural Value
6.	Tajjumaal Building	WO-1/ 61,	Wadhmal Oodharam (Nanakwara) Road, Daryalal Street;	Architectural Value
7.	Auqaf Building (S.C Lohana Company)	WO-2/ 3,	of Nishtar (Lawrence) Road, Hari Dodani Lane;	Architectural Value
8.	Raishami Building	WO-2/ 7,	Nishtar (Lawrence) Road;	Architectural Value
9.	Siddique Abdulallah Building	WO-2/ 13/ 1, 13/ 2,	off Wadhmal Oodharam (Nanakwara) Road, Hari Dodani Lane;	Architectural Value
10.	Ratanjee Building	WO-2/ 14/ 1, 14/ 2,	Hari Jethani Road, Hari Dodani Lane;	Architectural Value

11.	Mohammadi Manzil	WO-2/ 23,	James Terrace Road;	Architectural Value
12.	Siddhpur Masanewala Building/ Aisha Manzil	WO-2/ 34,	James Terrace Road, Najmudin Street;	Architectural Value
13.	Suthra Manzil	WO-2/ 35/ 1,	James Terrace Road, Najmudin Street;	Architectural Value
14.	Yousuf Ali Building	WO-2/ 35/ 2,	James Terrace Road, Najmudin Street;	Architectural Value
15.	Shereen Lakhpati Aukaf Building	WO-2/ 38,	James Terrace Road, Najmudin Street;	Architectural Value
16.	Antarya Building	WO-2/ 40,	Najmudin Street. Chand Bibi Road (Princess Street);	Architectural Value
17.	Water Tank	WO-3/ 1,	Police Line. Nishtar (Lawrence) Road;	Architectural Value
18.	Unknown	WO-3/ 5,	off Nishtar (Lawrence) Road;	Architectural Value
19.	Bhojani Building/ Parwani Building	WO-3/ 21,	James Terrace Road, Najmudin Street:	Architectural Value
20.	Tulsi Das Building	WO-3/ 28,	Chand Bibi Road (Princess Street), Najmudin Street;	Architectural Value
21.	Hajyani Khana Manzi	WO-4/ 4,	Bambayoge Road, off Nishtar (Lawrence) Road;	Architectural Value
22.	Yaqoob Khameesa Building	WO-4/ 10,	Ball Lane;	Architectural Value
23.	Ahmed Chemical Building	WO-4/ 13/ A,	James Terrace Road, Najmudin Street;	Architectural Value
24.	Mutala House	WO-4/ 13B,	Chand Bibi Road (Princess Street), Najmudin Street;	Architectural Value
25.	Naseem Building	WO-4/ 13C.	Bambayoge Road, Chand Bibi Road (Princess Street);	Architectural Value
26.	Ahmadi Building	WO-4/ 13D,	Bambayoge Road:	Architectural Value
27.	Tijori Building	WO-4/ 15/ 1,	Chand Bibi Road (Princess Street), Najmudin Street;	Architectural Value
28.	Hilal Mansion/ Zubaida Mansion	WO-4/ 15/ 2,	Chand Bibi Road (Princess Street), Najmudin Street;	Architectural Value
29.	Ronaqe Islamia School	WO-5/ 2,	Chand Bibi Road (Princess Street);	Architectural Value
30.	Lakhani Mansion	WO-5/ 5/ 1, 5/ 2,	Chand Bibi Road (Princess Street);	Architectural Value
31.	Baila Ram Building	WO-5/ 19,	Parathana Samaj Road;	Architectural Value
32.	Muhammadi Manzil	WO-5/ 22/ 1,	off Baba-e-Urdu (Mission) Road;	Architectural Value
33.	Najma Manzil	WO-5/ 22/ 2,	off Baba-e-Urdu (Mission) Road;	Architectural Value
34.	Fakhari Manzil	WO-5/ 22/ 3,	off Baba-e-Urdu (Mission) Road;	Architectural Value

35.	Khadija Manzil	WO-5/ 22/ 5,	off Baba-e-Urdu (Mission) Road;	Architectural Value
36.	Abdur Rasool Building	WO-5/ 22/ 7,	Baba-e-Urdu (Mission) Road;	Architectural Value
37.	Taleemgah-e-Niswan G.G.P.S	WO-5/ 23,	Chapa Street, All Dina Ali Mohammad Road;	Architectural Value
38.	Bojhwala Building	WO-6/ 1,	Adamjee Budhabhai Road, Parathana Samaj Road, Water Course Road;	Architectural Value
39.	Marvi Building	WO-6/8, 9,	Adamjee Budhabhai Road, Water Course Road;	Architectural Value
40.	Tahseen Manzil	WO-6/ 10, 11,	Adamjee Budhabhai Road, Water Course Road;	Architectural Value
41.	G. Marvi Building	WO-6/ 20,	M. A. Jinnah (Bunder) Road;	Architectural Value
42.	Sheikh Chamber	WO-6/ 23,	M. A. Jinnah (Bunder) Road, Adamji Budhabhai Road;	Architectural Value
43.	Saife Building	WO-6/ 25,	M. A. Jinnah (Bunder) Road;	Architectural Value
44.	Kanchwala Building	WO-6/ 28,	Adamjee Budhabhai Road;	Architectural Value
45.	Sawani Nawaz Building	WO-6/ 31,	Adamjee Budhabhai Road;	Architectural Value
46.	Capt. M. J. Khan Building	WO-6/ 33,	Adamjee Budhabhai Road;	Architectural Value
47.	Noor Manzil	WO-6/ 34/ 1,	Adamjee Budhabhai Road;	Architectural Value
48.	Bando Mandil Building	WO-6/ 36/ 1,	Parathana Samaj Road;	Architectural Value
49.	Shedai Manzil	WO-6/ 36/ 2,	Parathana Samaj Road;	Architectural Value
50.	Bulka Mansion	WO-6/ 36/ 3,	off Parathana Samaj Road;	Architectural Value
51.	Subhash Building	WO-6/ 37/ 1,	Parathana Samaj	Architectural Value
52.	Keshow Nivas Building	WO-6/ 42/ 1,	off Parathana Samaj Road;	Architectural Value
53.	Rehman Building	WO-6/ 44/ 2/ 1,	off M. A. Jinnah (Bunder) Road;	Architectural Value
54.	Manohar Mansion	WO-6/ 44/ 2/ 2,	off M. A. Jinnah (Bunder) Road;	Architectural Value
55.	Aftab Mansion	WO-6/ 44/ 2/ 3,	off M. A. Jinnah (Bunder) Road;	Architectural Value
56.	Premji Shama Building	WO-6/ 44/ 3,	off M. A. Jinnah (Bunder) Road;	Architectural Value
57.	Pyare Lal Building (Suraya)	WO-6/ 45/ 2/ 1, 45/ 2/ 2, 45/ 2/ 3,	off M. A. Jinnah (Bunder) Road;	Architectural Value

51

58.	Barkat Ali Building	WO-6/ 45/ 3,	off M. A. Jinnah (Blinder) Road, Shivandas Chandumal Road;	Architectural Value
59.	Ahtesham/ M. Laiq Mansion	WO-6/ 47, 51,	Shivandas Chandumal Road;	Architectural Value
60.	Unknown	WO-6/ 50, 54,	Shivandas Chandumal Road;	Architectural Value
61.	Hamaldas Manumal Building	WO-6/ 58/ 1,	Shivandas Chandumal Road;	Architectural Value
62.	Shakur Bhai Building	WO-6/ 58/ 2,	Shivandas Chandumal Road;	Architectural Value
63.	Mustujab Mansion	WO-6/ 60,	Shivandas Chandumal Road;	Architectural Value
64.	Filial Manzil	WO-6/ 63/ 1,	Shivandas Chandumal Road;	Architectural Value
65.	Govind Ram Katumal Building/ Khwaja Manzil	WO-6/ 64/ 1,	Shivandas Chandumal Road;	Architectural Value
66.	Mohammad Ali Budding	WO-6/ 64/ 2,	Shivandas Chandumal Road;	Architectural Value
67.	Jameel Mansion	WO-6/ 65/ 1,	Shivandas Chandumal Road;	Architectural Value
68.	Madhojee Premjee Building	WO-6/ 65/ 2,	Shivandas Chandumal Road;	Architectural Value
69.	Kanwarjee Dam Building	WO-6/ 66/ 1,	Shivandas Chandumal Road;	Architectural Value
70.	Bhatia Bhuwani Building/ Naveed Manzil	WO-6/ 66/ 2,	Shivandas Chandumal Road, Parathana Samaj Road;	Architectural Value
71.	Karishna Nawaz Building	WO-6/ 68/ 1,	Shivandas Chandumal Road, Parathana Samaj Road;	Architectural Value
72.	Shamoolal Kalyanjee Building	WO-6/ 69/ 1,	Shivandas Chandumal Road;	Architectural Value
73.	Santi Sadan	WO-6/ 69/ 2,	Shivandas Chandumal Road;	Architectural Value
74.	Unknown	WO-7/ 1,	Shahrah-e-Altai Hussain (Napier Road), Daryalal Street;	Architectural Value
75.	Fayz-e-Hussaini Mahal	WO-7/ 8, 9,	Shahrah-e-Altai Hussain (Napier Road);	Architectural Value
76.	Rehman Building (Zeeneth)	WO-7/ 19,	M. A. Jinnah (Bunder) Road;	Architectural Value
77.	Unknown	WO-7/ 32,	off Daryalal Street;	Architectural Value
78.	Abduhusen Karimjee Marvi Waqf Building	WO-8/ 8,	Chand Bibi Road (Princess Street), Chapa SInet;	Architectural Value
79.	Sabira Manzil	WO-8/ 10,	Chand Bibi Road (Princess Street), Chapa Street;	Architectural Value
80.	Family Park (Nanakwara Garden)	WO-3/ 19	James Terrace, Bambayoge Road	Architectural Value

81.	Karachi Muncpal Corporation Building	JAI-7/ 37,	M. A. Jinnah (Bunder) Road, Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
82.	Sarkari Madarsah-e-Awami (Amarat Kotwal Building)	JAI-6/ 73,	Baba-e-Urdu (Mission) Road, Parthana Samaj Road, Karachi	Architectural Value
83.	Faiz-e-Hussaini Trust Building	JAI-6/ 72,	Baba-e-Urdu (Mission) Road, M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
84.	Roshan Manzil	JAI-6/ 45, 55,	M. A. Jinnah (Bunder) Road, Shivdas Chandumal Road, Karachi	Architectural Value
85.	Ibrahimjee Hakimjee Building	JAI-6/ 35,	Parathana Samaj Road, Adamjee Budhabhai Road, Karachi	Architectural Value
86.	Small Causes Court	JAI-7/ 36,	M. A. Jinnah (Bunder) Road, Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
87.	Jahangir Kothari Building	JAI-7/ 18,	M. A. Jinnah (Bunder) Road, Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
88.	Adam Masjid	JAI-7/ 24,	Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
89.	Yousafi Manzil, Fayz-e Husayni Mahal	JAI-7/ 14,	Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
90.	Captain & Co. Building	JAI-7/ 13,	Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
91.	Karimjee Jivanjee School (Moriswala)	JAI-7/ 26, 27, 28,	Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
92.	Quetta Wala Building	JAI-7/ 5,	Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
93.	Farhana Building	JAI-7/ 3,	Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
94.	Post Office (City Court Compound)	JAI-8/ 19/ 1,	Chapa Street, Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
95.	Karachi Bar Association (City Court Compound)	JAI-8/ 19/ 1,	Lewis Road, Karachi	Architectural Value
96.	City Court	JAI-8/ 19/ 1,	Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
97.	Police Malkhana (City Court Compound)	JAI-8/ 19/ 1,	Lewis Road, Chapa Street, Karachi	Architectural Value
98.	Mulla Jafferjee Khandwala Building	JAI-1/ 18,	Shahrah-e-Altat Hussain (Napier Road), Mohammad Shah Street, Karachi	Architectural Value

99.	Sughrabai Trust Building	JAI-1/ 9,	Shahrah-e-Altat Hussain (Napier Road), Mohammad Shah Street, Karachi	Architectural Value
100.	Ahmed Khaliq & Co. Building	JAI-1/ 8,	Shahrah-e-Altat Hussain (Napier Road), Karachi	Architectural Value
101.	Budhabhai Building	JAI-1/ 15,	Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
102.	Adamali Sheikhjee Jewanjee Building	JAI-2/ 21,	James Terrace Road, Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
103.	Khandwala Building	JAI-2/ 20,	Wadhmal Oodharam (Nanakwara) Road, Hari Jethani Road, Karachi	Architectural Value
104.	Makhan Building	JAI-1/ 16, 17,	Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
105.	Auqaf Building	JAI-2/ 6,	Hari Dodani Lane, off Wadhmal Oodharam (Nanakwara) Road, Karachi	Architectural Value
106.	Muslim Ladies Technical and Industrial Institute	JAI-2/ 18a,	James Terrace Road, Karachi	Architectural Value
107.	Sundarjee Karamjee Building/ Premjee Kanwar Building	JAI-3/ 20,	James Terrace Road, Najmudin Street, Karachi	Architectural Value
108.	Edulji Dinshaw Building, Lady Dufferin Hospital	JAI-5/ 8,	Chand Bibi Road (Princess Street), Baba-e-Urdu (Mission) Road, Karachi	Architectural Value
109.	Bai Virabijee Katrak Maternity Wing, Laddy Dufferin Hospital	JAI-5/ 8,	Chand Bibi Road (Princess Street), Water Course Road, Karachi	Architectural Value
110.	Christ Church	JAI-4/ 11,	Baba-e-Urdu (Mission) Road, Nishtar (Lawrence) Road, Karachi	Architectural Value

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-
Secretary to Govt. of Sindh
Karachi dated the 26th April, 2018

No.OSD/CHC/JAILQ-01-49/2017

A copy is forwarded for information and necessary action to:-

1. The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
2. The Chairman, Planning & Development Board, Govt. of Sindh.
3. The Chairman, Technical Committee on Sindh Cultural Heritage.
4. The Administrative Secretaries (All), Government of Sindh.
5. The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
6. The Commissioner, Karachi.
7. The Director General, Sindh Building Control Authority.
8. The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
9. The Director (Heritage), CT&AD, Government of Sindh
10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
12. The Chief Executive Officer, Cantonment Board, Karachi.
13. The Deputy Commissioner-South, Karachi.
14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
16. The Owner / Occupant.
17. Notification File.

[Handwritten signature]
26/4/18

**SECTION OFFICER
(HERITAGE)**

For Secretary to Govt. of Sindh



ADDENDUM-01

(55)

GOVERNMENT OF SINDH
CULTURE, TOURISM &
ANTIQUITIES DEPARTMENT

NOTIFICATION

No.OSD/CHC/JAILQ/01-49/2017:(ADDENDUM-01)In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(JAIL QUARTERS)

S.NO.	NAME OF BUILDING	PLOT #	ADDRESS	REASON FOR ENLISTMENT AS HERITAGE
111.	Jahangir Mansion	WO- 6/ 57,	M. A. Jinnah (Bunder) Road, ShivdasChandumal Road	Architectural Value
112.	Unknown	WO-2/ 28/1,28/2	Najmudin Streed James Terrace Road	Architectural Value

Not Forward in List.

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-
Secretary to Govt. of Sindh
Karachi dated the November. 2019

No. OSD/CHC/JAILQ/01-49/2017

A copy is forwarded for information and necessary action to:-

1. The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
2. The Chairman, Planning & Development Board, Govt. of Sindh.
3. The Chairman, Technical Committee on Sindh Cultural Heritage.
4. The Administrative Secretaries (All), Government of Sindh.
5. The Commissioner, Karachi.

6. The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
7. The Director General, Sindh Building Control Authority.
8. The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
9. The Director (Heritage), CT&AD, Government of Sindh
10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
12. The Chief Executive Officer, Cantonment Board, Karachi.
13. The Deputy Commissioner-South, Karachi.
14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
16. PS to Secretary, Culture, Tourism & Antiquities Department, Govt. of Sindh.
17. The Owner / Occupant.
18. Notification File.

[Signature] 28/11/19.

SECTION OFFICER
(HERITAGE)
For Secretary to Govt. of Sindh

**KARACHI HERITAGE BUILDINGS
RE-SURVEY PROJECT**




JAIL QUARTER


**CULTURE, TOURISM AND ANTIQUITIES
DEPARTMENT**

GOVERNMENT OF SINDH


KARACHI MUNICIPAL CORPORATION BUILDING

	1. IDENTIFICATION:		
	Site Name:	Karachi Municipal Corporation Building	
	Other Names:	---	
	2. LOCATION:		
	Address:	JAI-7/ 37, M. A. Jinnah (Bunder) Road, Shahrah-e-Altah Hussain (Napier Road)	
	Survey No.	Plot No. 7/ 37, Sheet No.	
	Coordinates	N-24.855421 E-67.007507	
	District/City/ Town	Karachi	
3. OWNERSHIP:		Private Government ✓	
Name of Owner (s)	GOVERNMENT OF SINDH		
4	OCCUPANCY	G+2 (Civic Amenity)	
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Entrance portal, Dome, Clock Tower, Cornices/ Moldings)	
6	MEASUREMENT	Height-60' Length-250' Breath-150' Approximately	
7	CONSTRUCTION MATERIAL	Stone building	
8	STATUS/PRESENT CONDITION	Dilapidated	Stable Good Condition ✓ Needs repair
9	THEREAT(S)	Good state of condition	
10	LOCATION MAP		
			
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. Building was constructed in 1851.</i>	
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>	
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi	
14	DATE	28-02-2018	


SMALL CAUSES COURT

	1. IDENTIFICATION:			
	Site Name:	Small Causes Court		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-7/ 36, M. A. Jinnah (Bunder) Road, Shahrāh-e-Altāf Hussain (Napier Road)		
	Survey No.	Plot No. 7/ 36	Sheet No.	
	Coordinates	N-24.0154595	E-67.006577	
	District/City/ Town	Karachi		
	3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
	Name of Owner (s)	GOVERNMENT OF SINDH		
4 OCCUPANCY	G+2 (Civic amenity)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Pediments, Entrance, Portal, Royal Crest, Timber pitched roof and iron grill works)			
6 MEASUREMENT	Height-19'.10" Length-170' Breath-51' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. Building was constructed in 1922.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	28-02-2018			


ADAM MASJID

	1. IDENTIFICATION:				
	Site Name:		Adam Masjid		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-7/ 24, Wadhmal Oodharam (Nanakwara) Road		
	Survey No.		Plot No. 7/ 24	Sheet No.	
	Coordinates		N-24.854784	E-67.006089	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)		TRUST			
4	OCCUPANCY	Religious Place			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Cornices/ Molding, Dome, Cupola, Pilasters, Decorative Parapet, Courtyard, Minarate)			
6	MEASUREMENT	Height-19' Length-98' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair	
9	THEREAT(S)	Good state of condition			
10	LOCATION MAP	<p><i>PHOTOGRAPH(s)</i></p> <div style="display: flex; flex-wrap: wrap;">      </div>			
11	COMMENTS	<i>The Masjid was constructed in 1993 and Well maintained. Its architectural features correspond to the Mughal Period..</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its religious and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	28-02-2018			


KARIMJEE JIVANJEE SCHOOL (MORISWALA)

	1.	IDENTIFICATION:				
		Site Name:	Karimjee Jivanjee School (Moriswala)			
		Other Names:	---			
	2.	LOCATION:				
		Address:	JAI-7/ 26, 27, 28, Wadhmal Oodharam (Nanakwara) Road			
		Survey No.	Plot No. 7/ 26, 27, 28,	Sheet No.		
		Coordinates	N-24.855290	E-67.005561		
		District/City/ Town	Karachi			
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/> Government		
		Name of Owner (s)	TRUST			
4	OCCUPANCY		G+3 -Institutional (School)			
5	REASONS FOR PROTECTION		Architectural Value: (Pediments, Colonnaded, Arcaded, verandah, Courtyard)			
6	MEASUREMENT		Height-55' Length-98' Breath-64' Approximately			
7	CONSTRUCTION MATERIAL		Stone building			
8	STATUS/PRESENT CONDITION		Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)		Second degree threat			
10	LOCATION MAP		PHOTOGRAPH(S)			
						
11	COMMENTS		<i>British period Historical back ground and architectural features of the building are sound. The School was constructed in 1931.</i>			
12	RECOMMENDATIONS		<i>The building deserves to be declared as protected heritage due to its social, historical and architectural value.</i>			
13	NAME OF INVESTIGATOR		Muhammad Omar Qureshi			
14	DATE		28-02-2018			


CITY COURT

	1. IDENTIFICATION:				
	Site Name:		City Court		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-8/ 19/ 1, Wadhmal Oodharam (Nanakwara) Road		
	Survey No.		Plot No. 8/ 19/ 1	Sheet No.	
	Coordinates		N-24.855610	E-67.005918	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>		
Name of Owner (s)		GOVERNMENT OF SINDH			
4	OCCUPANCY	G+2 (Civic Amenity)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Pediments, Entrance Portal, Royal Crest, Timber Pitched Roof, Pilasters, Arcaded Verandah, Cornices/ Moldings)			
6	MEASUREMENT	Height-51' Length-238' Breath-40' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair	
9	THEREAT(S)	Good state of condition			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	28-02-2018			


POST OFFICE (CITY COURT COMPOUND)

	1. IDENTIFICATION:			
	Site Name:		Post Office (City Court Compound)	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-8/ 19/ 1, Chapa Street, Wadhmal Oodharam (Nanakwara) Road	
	Survey No.		Plot No. 8/19/1,	Sheet No.
	Coordinates		N-24.856282	E-67.005479
	District/City/ Town		Karachi	
3. OWNERSHIP:		Private	Government ✓	
Name of Owner (s)		GOVERNMENT OF SINDH		
4	OCCUPANCY	G+1 (Civic Amenity)		
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Roundels, Timber pitched roof)		
6	MEASUREMENT	Height-23' Length-123' Breath-43' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition
9	THEREAT(S)	Second degree threat		
10	LOCATION MAP	PHOTOGRAPH(S)		
				
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	28-02-2018		


POLICE MALKHANA (CITY COURT COMPOUND)

	1. IDENTIFICATION:				
	Site Name:		Police Malkhana (City Court Compound)		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-8/ 19/ 1, Lewis Road, Chapa Street		
	Survey No.		Plot No. 8/19/1	Sheet No.	
	Coordinates		N-24.856612	E-67.005917	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>		
Name of Owner (s)		GOVERNMENT OF SINDH			
4	OCCUPANCY	(Rented) G+1 (Civic Amenity)			
5	REASONS FOR PROTECTION	Architectural Value: (Timber pitched roof and bossed stone masonry)			
6	MEASUREMENT	Height-25' Length-232' Breath-48' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	
9	THEREAT(S)	Good state of condition			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	28-02-2018			



KARACHI BAR ASSOCIATION (CITY COURT COMPOUND)

	1. IDENTIFICATION:			
	Site Name:	Karachi Bar Association (City Court Compound)		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-8/ 19/ 1, Lewis Road		
	Survey No.	Plot No. 8/ 19	Sheet No.	
	Coordinates	N-24.855816	E-67.006673	
District/City/ Town	Karachi			
3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>		
Name of Owner (s)	GOVERNMENT OF SINDH			
4 OCCUPANCY	G+1 (Civic Amenity)			
5 REASONS FOR PROTECTION	Architectural Value: (Colonnaded and verandah)			
6 MEASUREMENT	Height-32' Length-150' Breath-30' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP	PHOTOGRAPH(S)			
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	28-02-2018			


TAIJUMAL BUILDING

	1. IDENTIFICATION:				
	Site Name:		Tajjumul Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-1/61, Wadhmal Oodharam (Nanakwara) Road, Daryalal Street		
	Survey No.		Plot No. 1/61	Sheet No.	
	Coordinates		N-24.855708	E-67.005269	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>		Government	
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches and Decorative Parapet)			
6	MEASUREMENT	Height-'46 Length-'70' Breath-'32' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/>	
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	28-02-2018			

QUEETA WALA BUILDING

	1. IDENTIFICATION:			
	Site Name:		Queeta Wala Building	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-7/ 5, Shahrah-e-Altah Hussain (Napier Road)	
	Survey No.		Plot No. 7/ 5	Sheet No.
	Coordinates		N-24.855132	E-67.004689
	District/City/ Town		Karachi	
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s)		UNKNOWN	
4	OCCUPANCY	(Rented) G+2+2 (Commercial)		
5	REASONS FOR PROTECTION	Architectural Value: (Roundals, Arches, Cornices, Molding, Pilasters)		
6	MEASUREMENT	Height-47' Length-30' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat		
10	LOCATION MAP	PHOTOGRAPH(S)		
				
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	28-02-2018		


FARHANA BUILDING

	1. IDENTIFICATION:			
	Site Name:		Farhana Building	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-7/3, Shahrah-e-Altaf Hussain (Napier Road)	
	Survey No.		Plot No. 7/3	Sheet No.
	Coordinates		N-24.855255	E-67.004540
	District/City/ Town		Karachi	
	3. OWNERSHIP:		Private ✓	Government
	Name of Owner (s)		UNKNOWN	
4 OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Cornices/ Moldings, Pilasters, Decorative Parapet)			
6 MEASUREMENT	Height-37' Length-23' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP	PHOTOGRAPH(s)			
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	01-03-2018			


YOUSAFI MANZIL, FAYZ-E-HUSAYNI MAHAL

	1. IDENTIFICATION:				
	Site Name:		Yousafi Manzil, Fayz-e-Husayni Mahal		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-7/ 14, Shahrah-e-Altah Hussain (Napier Road)		
	Survey No.		Plot No. 7/ 14	Sheet No.	
	Coordinates		N-24.854569	E-67.005048	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		TRUST			
4	OCCUPANCY	(Rented) G+2 (Commercial)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Pediments, Cornices/ Moldings, Pilasters, Decorative Parapet)			
6	MEASUREMENT	Height-58' Length-59' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP				
		PHOTOGRAPH(S) 			
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. The Building was constructed in 1910.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	01-03-2018			


JAHANGIR KOTHARI BUILDING

	1. IDENTIFICATION:				
	Site Name:		Jahangir Kothari Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-7/ 18, M. A. Jinnah (Bunder) Road, Shahrah-e-Altaf Hussain (Napier Road)		
	Survey No.		Plot No. 7/ 18	Sheet No.	
	Coordinates		N-24.853829	E-67.005422	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		TRUST			
4	OCCUPANCY	(Rented) G+2 (Commercial)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Coupled Column, Pediments, Decorative Parapet, Pilasters, Cornices/ Molding, Arcade/ Portico, Tower, Courtyard, Timber Pitched Roof)			
6	MEASUREMENT	Height-30' Length-145' Breath-42' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. The Building was constructed in 1922.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	01-03-2018			

ANTARYA BUILDING

	1. IDENTIFICATION:				
	Site Name:		Antarya Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-2/ 40, Najmudin Street, Chand Bibi Road (Princess Street)		
	Survey No.		Plot No. 2/ 40	Sheet No.	
	Coordinates		N-24.51316	E-67.00267	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	G+3 (Vacant)			
5	REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Pilasters, Decorative Parapet, Cornices/ Molding)			
6	MEASUREMENT	Height-44' Length-48' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated ✓	Stable	Good Condition	Needs repair
9	THEREAT(S)	High degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. Building is required immediate repair.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	01-03-2018			


EDULJI DINSHAW BUILDING, LADY DUFFERIN HOSPITAL

	1. IDENTIFICATION:			
	Site Name:	Edulji Dinshaw Building, Lady Dufferin Hospital		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-5/ 8, Chand Bibi Road (Princess Street), Baba-e-Urdu (Mission) Road		
	Survey No.	Plot No. 5/ 8	Sheet No.	
	Coordinates	N-24.15813	E-67.00498	
District/City/ Town	Karachi			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	TRUST			
4 OCCUPANCY	(Hospital) G+1			
5 REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Pediments, Gargoyles, Cornices/ Moldings, Pilasters, Decorative Parapet)			
6 MEASUREMENT	Height-26' Length-193' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9 THEREAT(S)	Well maintained			
10 LOCATION MAP				
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. The Building was constructed during 1894-1898.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its social, historical and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	01-03-2018			


BAI VIRBAIJEE KATRAK MATERNITY WING, LADDY DUFFERIN HOSPITAL

	1. IDENTIFICATION:			
	Site Name:	Bai Virbaijee Katrak Maternity Wing, Laddy Dufferin Hospital		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-5/ 8, Chand Bibi Road (Princess Street), Water Course Road		
	Survey No.	Plot No. 5/ 8	Sheet No.	
	Coordinates	N-24.51501	E-67.00491	
	District/City/ Town	Karachi		
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	TRUST			
4 OCCUPANCY	(Hospital) G+6			
5 REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Pilasters, Pediments, Decorative Parapet)			
6 MEASUREMENT	Height-26' Length-101' Breath-' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9 THEREAT(S)	Well maintained			
10 LOCATION MAP	PHOTOGRAPH(s)			
	 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. The Building was constructed in 1916.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its social, historical and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	01-03-2018			


SHEREEN LAKHPATI AUKAF BUILDING

	1. IDENTIFICATION:			
	Site Name:	Shereen Lakhpati Aukaf Building		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-2/ 38, James Terrace Road, Najmudin Street		
	Survey No.	Plot No. 2/ 38	Sheet No.	
	Coordinates	N-24.51484	E-67.00365	
	District/City/ Town	Karachi		
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	TRUST			
4 OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Pilasters, Decorative Parapet)			
6 MEASUREMENT	Height-26' Length-58' Breath-49' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
	PHOTOGRAPH(S) 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its social and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	02-03-2018			


SUNDARJEE KARAMJEE BUILDING/ PREMJEE KANWAR BUILDING

	1. IDENTIFICATION:			
	Site Name:	Sundarjee Karamjee Building/ Premjee Kanwar Building		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-3/ 20, James Terrace Road, Najmudin Street		
	Survey No.	Plot No. 3/ 20	Sheet No.	
	Coordinates	N-24.51491	E-67.00372	
District/City/ Town	Karachi			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	UNKNOWN			
4 OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Pilasters, Decorative Parapet and iron grill works)			
6 MEASUREMENT	Height-34' Length-67' Breath-38' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	02-03-2018			


BHOJANI BUILDING/ PARWANI BUILDING

	1. IDENTIFICATION:				
	Site Name:		Bhojani Building/ Parwani Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-3/21, James Terrace Road, Najmudin Street		
	Survey No.		Plot No. 3/21	Sheet No.	
	Coordinates		N-24.51507	E-67.00383	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+3+1 (GF. Commercial, 1st, 2nd,3rd and 4th floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches and Balconies)			
6	MEASUREMENT	Height-'54 Length-'70' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat (4th floor new constructed)			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	02-03-2018			


MUSLIM LADIES TECHNICAL AND INDUSTRIAL INSTITUTE

	1.	IDENTIFICATION:			
		Site Name:	Muslim Ladies Technical and Industrial Institute		
		Other Names:	---		
	2.	LOCATION:			
		Address:	JAI-2/ 18a, James Terrace Road		
		Survey No.	Plot No. 2/ 18a	Sheet No.	
		Coordinates	N-24.51457	E-67.00298	
		District/City/ Town	Karachi		
	3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s)	TRUST		
4	OCCUPANCY	(Rented) Ground floor (Institution)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Pilasters, Decorative Parapet, Pediments and iron grill works)			
6	MEASUREMENT	Height-16' Length-194' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9	THEREAT(S)	Good state of condition			
10	LOCATION MAP	PHOTOGRAPH(s)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. The Building was constructed in 1914.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its social, historical and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	02-03-2018			


SIDDHPUR MASANEWALA BUILDING/AISHA MANZIL

	1. IDENTIFICATION:			
	Site Name:	Siddhpur Masanewala Building/ Aisha Manzil		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-2/ 34, James Terrace Road, Najmudin Street		
	Survey No.	Plot No. 2/ 34	Sheet No.	
	Coordinates	N-24.51452	E-67.00313	
	District/City/ Town	Karachi		
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	UNKNOWN		
4 OCCUPANCY	(Rented) G+3+1 (GF. Commercial, 1st, 2nd, 3rd and 4th floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Balconies, Pilasters, Decorative Parapet, iron grill works)			
6 MEASUREMENT	Height-55' Length-23' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat (4th floor newly constructed)			
10 LOCATION MAP				
	PHOTOGRAPH(S) 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	02-03-2018			


SUNDARJEE KARAMJEE BUILDING (CALCUTTA BUILDING)

	1. IDENTIFICATION:			
	Site Name:	Sundarjee Karamjee Building (Calcutta Building)		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-2/ 54, Chand Bibi Road (Princess Street), Najmudin Street		
	Survey No.	Plot No. 2/ 54	Sheet No.	
	Coordinates	N-24.51526	E-67.80402	
	District/City/ Town	Karachi		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	UNKNOWN			
4 OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches and bossed stone masonry)			
6 MEASUREMENT	Height-' Length-' Breath-' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated <input checked="" type="checkbox"/>	Stable	Good Condition	Needs repair
9 THEREAT(S)	Part Destroyed			
10 LOCATION MAP				
	PHOTOGRAPH(S) 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	05-03-2018			


YOUSUF ALI BUILDING

	1.	IDENTIFICATION:		
		Site Name:	Yousuf Ali Building	
		Other Names:	---	
	2.	LOCATION:		
		Address:	JAI-2/ 35/ 2, James Terrace Road, Najmudin Street	
		Survey No.	Plot No. 2/ 35/ 2	Sheet No.
		Coordinates	N-24.51525	E-67.00402
		District/City/ Town	Karachi	
	3.	OWNERSHIP:		
			Private ✓	Government
	Name of Owner (s)	UNKNOWN		
4	OCCUPANCY		(Rented) G+3+1 (GF. Commercial, 1st, 2nd, 3rd and 4th floor residential)	
5	REASONS FOR PROTECTION		Architectural Value: (Balconies, Pilasters, Decorative Parapet, Pediments, Festoons)	
6	MEASUREMENT		Height-' Length-' Breath-' Approximately	
7	CONSTRUCTION MATERIAL		Stone building	
8	STATUS/PRESENT CONDITION		Dilapidated Stable Good Condition Needs repair ✓	
9	THEREAT(S)		Second degree threat (4th floor new constructed)	
10	LOCATION MAP		PHOTOGRAPH(S)	
				
11	COMMENTS		<i>British period Historical back ground and architectural features of the building are sound.</i>	
12	RECOMMENDATIONS		<i>The building deserves to be declared as protected heritage due to its architectural value.</i>	
13	NAME OF INVESTIGATOR		Muhammad Omar Qureshi	
14	DATE		05-03-2018	



SUGHRA MANZIL

	1. IDENTIFICATION:			
	Site Name:	Sughra Manzil		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-2/35/1, James Terrace Road, Najmudin Street		
	Survey No.	Plot No. 2/35/1	Sheet No.	
	Coordinates	N-24.51526	E-67.00402	
	District/City/ Town	Karachi		
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	UNKNOWN		
4 OCCUPANCY	(Rented) G+3+1 (GF. Commercial, 1st, 2nd, 3rd and 4th floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Balconies, Pilasters, Decorative Parapet,)			
6 MEASUREMENT	Height-57' Length-53' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat (4th floor new constructed)			
10 LOCATION MAP				
	PHOTOGRAPH(S) 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	05-03-2018			


MOHAMMADI MANZIL

	1.	IDENTIFICATION:			
		Site Name:	Mohammadi Manzil		
		Other Names:	---		
	2.	LOCATION:			
		Address:	JAI-2/23, James Terrace Road		
		Survey No.	Plot No. 2/ 23	Sheet No.	
		Coordinates	N-24.51441	E-67.00273	
		District/City/ Town	Karachi		
	3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s)	UNKNOWN		
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Balconies, Pilasters, Decorative Parapet and iron grill works)			
6	MEASUREMENT	Height-47' Length-38' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	05-03-2018			


ADAMALI SHEIKHJEE JEWANJEE BUILDING

	1. IDENTIFICATION:				
	Site Name:		Adamali Sheikhjee Jewanjee Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-2/ 21, James Terrace Road, Wadhmal Oodharam (Nanakwara) Road		
	Survey No.		Plot No. 2/ 21	Sheet No.	
	Coordinates		N-24.51433	E-67.00256	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Cornices/ Moldings, Pilasters, Decorative Parapet, Bossed Stone masonry and iron grill works)			
6	MEASUREMENT	Height-37' Length-47' Breath-37' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	06-03-2018			

TAPAL HOUSE

	1. IDENTIFICATION:			
	Site Name:	Tapal House		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-1/ 24, Wadhmal Oodharam (Nanakwara) Road, Mohammad Shah Street		
	Survey No.	Plot No. 1/ 24	Sheet No.	
	Coordinates	N-24.51432	E-67.00246	
	District/City/ Town	Karachi		
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	UNKNOWN		
4 OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Pilasters, Cornices/ Moldings)			
6 MEASUREMENT	Height-35' Length-58' Breath-45' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated <input type="checkbox"/>	Stable <input type="checkbox"/>	Good Condition <input type="checkbox"/>	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
	PHOTOGRAPH(S) 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	06-03-2018			


KHANDWALA BUILDING

	1. IDENTIFICATION:				
	Site Name:		Khandwala Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-2/ 20, Wadhmal Oodharam (Nanakwara) Road, Hari Jethani Road		
	Survey No.		Plot No. 2/ 20	Sheet No.	
	Coordinates		N-24.51455	E-67.00233	
District/City/ Town		Karachi			
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Cornices/ Moldings, Pilasters, Decorative Parapet, Timber pitched roof and Courtyard)			
6	MEASUREMENT	Height-38' Length-120' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	
9	THEREAT(S)	High degree threat			
10	LOCATION MAP				
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	06-03-2018			


RATANJEE BUILDING

	1. IDENTIFICATION:			
	Site Name:	Ratanjee Building		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-2/ 14/ 1, 14/ 2, Hari Jethani Road, Hari Dodani Lane		
	Survey No.	Plot No. 2/ 14/ 1, 14/ 2	Sheet No.	
	Coordinates	N-24.51476	E-67.00269	
District/City/ Town	Karachi			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	UNKNOWN			
4 OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Cornices/ Moldings, Pilasters, Decorative Parapet and iron grill works)			
6 MEASUREMENT	Height-43' Length-39' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	06-03-2018			


AUQAF BUILDING

	1. IDENTIFICATION:			
	Site Name:		Auqaf Building	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-2/ 6, Hari Dodani Lane, off Wadhmal Oodharam (Nanakwara) Road	
	Survey No.		Plot No. 2/ 6	Sheet No.
	Coordinates		N-24.51486	E-67.00240
	District/City/ Town		Karachi	
3. OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>	
Name of Owner (s)		TRUST		
4	OCCUPANCY	(Rented) G+1 (GF. Commercial, 1st floor residential)		
5	REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Cornices/ Moldings, Pilasters, Decorative Parapet)		
6	MEASUREMENT	Height-'20 Length-57' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat		
10	LOCATION MAP			
		PHOTOGRAPH(S) 		
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	07-03-2018		


SIDDIQUE ABDULALLAH BUILDING

	1. IDENTIFICATION:				
	Site Name:		Siddique Abdulallah Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-2/ 13/ 1, 13/ 2, off Wadhmal Oodharam (Nanakwara) Road, Hari Dodani Lane		
	Survey No.		Plot No. 2/ 13/ 1, 13/ 2	Sheet No.	
	Coordinates		N-24.51486	E-67.00236	
	District/City/ Town		Karachi		
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+2+1 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Pilasters, Decorative Parapet)			
6	MEASUREMENT	Height-43' Length-38' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	
9	THEREAT(S)	Second degree threat (third floor new constructed)			
10	LOCATION MAP				
		PHOTOGRAPH(S) 			
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	07-03-2018			


AUQAF BUILDING (S.C LOHANA COMPANY)

	1. IDENTIFICATION:			
	Site Name:		Auqaf Building (S.C Lohana Company)	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-2/ 3, off Nishtar (Lawrence) Road, Hari Dodani Lane	
	Survey No.		Plot No. 2/ 3	Sheet No.
	Coordinates		N-24.51506	E-67.00267
District/City/ Town		Karachi		
3. OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>	
Name of Owner (s)		TRUST		
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)		
5	REASONS FOR PROTECTION	Architectural Value: (Arches and Decorative Parapet)		
6	MEASUREMENT	Height-48' Length-117' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat		
10	LOCATION MAP			
		PHOTOGRAPH(S) 		
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	07-03-2018		


RAISHAMI BUILDING

	1. IDENTIFICATION:				
	Site Name:		Raishami Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-2/ 7, Nishtar (Lawrence) Road		
	Survey No.		Plot No. 2/ 7	Sheet No.	
	Coordinates		N-24.51532	E-67.00247	
District/City/ Town		Karachi			
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Bossed stone masonry, Timber pitched roof)			
6	MEASUREMENT	Height-37' Length-53' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	07-03-2018			


BUDHABHAI BUILDING

	1. IDENTIFICATION:			
	Site Name:		Budhabhai Building	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-1/ 15, Wadhmal Oodharam (Nanakwara) Road	
	Survey No.		Plot No. 1/ 15	Sheet No.
	Coordinates		N-24.51465	E-67.00223
	District/City/ Town		Karachi	
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s)		UNKNOWN	
4	OCCUPANCY	(Rented) G+3+1 (GF. Commercial, 1st, 2nd, 3rd and 4th floor residential)		
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Cornices/ Moldings, Pilasters, Decorative Parapet, and iron grill works)		
6	MEASUREMENT	Height-30' Length-30' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat (4th floor new constructed)		
10	LOCATION MAP	 		
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	07-03-2018		


MAKHAN BUILDING

	1. IDENTIFICATION:				
	Site Name:		Makhhan Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-1/ 16, 17, Wadhmal Oodharam (Nanakwara) Road		
	Survey No.		Plot No. 1/16, 17	Sheet No.	
	Coordinates		N-24.51476	E-67.00225	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Roundals, Arches, Cornices/ Moldings, Pilasters, Decorative Parapet, and iron grill works)			
6	MEASUREMENT	Height-52' Length-104' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP				
		PHOTOGRAPH(S) 			
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	08-03-2018			


MULLA JAFFERJEE KHANDWALA BUILDING

	1. IDENTIFICATION:			
	Site Name:		Mulla Jafferjee Khandwala Building	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-1/ 18, Shahrah-e-Altat Hussain (Napier Road), Mohammad Shah Street	
	Survey No.		Plot No. 1/ 18	Sheet No.
	Coordinates		N-24.51428	E-67.00217
	District/City/ Town		Karachi	
	3. OWNERSHIP:		Private ✓	Government
	Name of Owner (s)		UNKNOWN	
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd & 3rd floor residential)		
5	REASONS FOR PROTECTION	Architectural Value: (Cornices/ Moldings, Pilasters, Decorative Parapet, and iron grill works)		
6	MEASUREMENT	Height-523' Length-73' Breath-53' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition
9	THEREAT(S)	Needs repair ✓		
9	THEREAT(S)	Second degree threat		
10	LOCATION MAP			
		PHOTOGRAPH(S) 		
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	08-03-2018		


SUGHRABAI TRUST BUILDING

	1. IDENTIFICATION:			
	Site Name:	Sughrabai Trust Building		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-1/ 9, Shahrah-e-Altah Hussain (Napier Road), Mohammad Shah Street		
	Survey No.	Plot No. 1/ 9	Sheet No.	
	Coordinates	N-24.51422	E-67.00205	
District/City/ Town	Karachi			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	TRUST			
4 OCCUPANCY	(Rented) G+2 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Roundals, Arches, Cornices/ Moldings, Pilasters, Decorative Parapet, and iron grill works)			
6 MEASUREMENT	Height-34' Length-73' Breath 52'.3" Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
	PHOTOGRAPH(S) 			
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	08-03-2018			


AHMED KHALIQ & CO. BUILDING

	1. IDENTIFICATION:	
	Site Name:	Ahmed Khaliq & Co. Building
	Other Names:	---
	2. LOCATION:	
	Address:	JAI-1/ 8, Shahrah-e-Altat Hussain (Napier Road)
	Survey No.	Plot No. 1/ 8 Sheet No.
	Coordinates	N-24.51426 E-67.00192
District/City/ Town	Karachi	
3. OWNERSHIP:		Private <input checked="" type="checkbox"/> Government
Name of Owner (s)		TRUST
4	OCCUPANCY	(Rented) G+1+1 (GF. Commercial, 1st & 2nd floor residential)
5	REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Cornices/ Moldings, Pilasters, Decorative Parapet, and iron grill works)
6	MEASUREMENT	Height-24' Length-29' Breath-' Approximately
7	CONSTRUCTION MATERIAL	Stone building
8	STATUS/PRESENT CONDITION	Dilapidated Stable Good Condition Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat (2nd floor new constructed)
10	LOCATION MAP	PHOTOGRAPH(s)
		
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi
14	DATE	08-03-2018


NIGAR CINEMA

	1. IDENTIFICATION:			
	Site Name:	Nigar Cinema		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-1/ 1, Shahrah-e-Altaf Hussain (Napier Road), Nishtar (Lawrence) Road		
	Survey No.	Plot No. 1/ 1	Sheet No.	
	Coordinates	N-24.51482	E-67.00173	
	District/City/ Town	Karachi		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	UNKNOWN			
4 OCCUPANCY	(Rented) G+2 (GF. Commercial)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Balconies, Cornices/ Moldings, Pilasters and sculpture)			
6 MEASUREMENT	Height-40' Length-103' Breath-123' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated <input checked="" type="checkbox"/>	Stable	Good Condition	Needs repair
9 THEREAT(S)	High degree threat			
10 LOCATION MAP	PHOTOGRAPH(s)			
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	08-03-2018			


WATER TANK

	1. IDENTIFICATION:			
	Site Name:		Water Tank	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-3/ 1, Police Line, Nishtar (Lawrence) Road	
	Survey No.		Plot No. 3/ 1	Sheet No.
	Coordinates		N-24.51537	E-67.00333
	District/City/ Town		Karachi	
	3. OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>
	Name of Owner (s)		GOVERNMENT OF SINDH	
4	OCCUPANCY	(Rented) G+4 (GF. 1st & 2nd floor Stairs and 4th floor water tank)		
5	REASONS FOR PROTECTION	Architectural Value: (Arches)		
6	MEASUREMENT	Height-63' Length-4' Breath-4' Approximately		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat		
10	LOCATION MAP	PHOTOGRAPH(S)		
				
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its social, historical and architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	09-03-2018		



CHRIST CHURCH

	1. IDENTIFICATION:			
	Site Name:		Christ Church	
	Other Names:		---	
	2. LOCATION:			
	Address:		JAI-4/ 11, Baba-e-Urdu (Mission) Road, Nishtar (Lawrence) Road	
	Survey No.		Plot No. 4/ 11	Sheet No.
	Coordinates		N-24.51679	E-67.00440
	District/City/ Town		Karachi	
3. OWNERSHIP:		Private ✓	Government	
Name of Owner (s)		MISSIONARY ORGANIZATION PROPERTY		
4	OCCUPANCY	Religious Church		
5	REASONS FOR PROTECTION	Architectural Value: (Arches, Buttresses, Bulls eye / Rose windows, Timber pitched roof, Roundels and cornices)		
6	MEASUREMENT	No permission for measurement		
7	CONSTRUCTION MATERIAL	Stone building		
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓ Needs repair
9	THEREAT(S)	Well maintained		
10	LOCATION MAP			
		PHOTOGRAPH(S) 		
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>		
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its religious, historical and architectural value.</i>		
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi		
14	DATE	09-03-2018		


UNKNOWN

	1. IDENTIFICATION:			
	Site Name:	Unknown-000937		
	Other Names:	---		
	2. LOCATION:			
	Address:	Jai-3/5, Off Nishtar (Lawrence) Road		
	Survey No.	Plot No. 3/ 5	Sheet No.	
	Coordinates	N-24.51610	E-67.00340	
	District/City/ Town	Karachi		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	UNKNOWN			
4 OCCUPANCY	(Rented) Ground Floor Commercial, 1st floor Vacant and 2nd Floor Destroyed)			
5 REASONS FOR PROTECTION	Architectural Value: (Pilasters, Decorative Parapet)			
6 MEASUREMENT	Height-22' Length-28' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated <input checked="" type="checkbox"/>	Stable	Good Condition	Needs repair
9 THEREAT(S)	High degree threat (3rd floor new constructed)			
10 LOCATION MAP	PHOTOGRAPH(S) <div style="display: flex; justify-content: space-around;">   </div>			
11 COMMENTS	<i>Partially demolished British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	09-03-2018			


HAJYANI KHATTA MANZIL

	1. IDENTIFICATION:				
	Site Name:		Hajyani Khatta Manzil		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-4/ 4, Bambayoge Road, off Nishtar (Lawrence) Road		
	Survey No.		Plot No. 4/ 4	Sheet No.	
	Coordinates		N-24.51621	E-67.00363	
	District/City/ Town		Karachi		
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)		TRUST		
4 OCCUPANCY	(Rented) G+2+1 (GF. Commercial, 1st, 2nd and 3rd floor residential)				
5 REASONS FOR PROTECTION	Architectural Value: (Balconies, Pediments and Pilasters,)				
6 MEASUREMENT	Height-43' Length-40' Breath-31' Approximately				
7 CONSTRUCTION MATERIAL	Stone building				
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>	
9 THEREAT(S)	Second degree threat (3rd floor new constructed)				
10 LOCATION MAP	PHOTOGRAPH(s)				
					
					
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>				
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>				
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi				
14 DATE	09-03-2018				



FAIZ-E-HUSSAINI TRUST BUILDING

	1. IDENTIFICATION:				
	Site Name:		Faiz-e-Hussaini Trust Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-6/ 72, Baba-e-Urdu (Mission) Road, M. A. Jinnah (Bunder) Road		
	Survey No.		Plot No. JAI-6/72	Sheet No.	
	Coordinates		N-24.51410	E-67.00627	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private ✓	Government		
Name of Owner (s)		TRUST			
4	OCCUPANCY	G+1 (GF. Commercial and 1st floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Roundels, Arches, Pilasters, Pediments, Cornices/ Molding, Decorative Parapet, Colonnaded/ Arcaded Verandah)			
6	MEASUREMENT	Height-27' Length-187' Breath-84' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	09-03-2018			


SARKARI MADARSAH-E-AWAMI (AMARAT KOTWAL BUILDING)

	1. IDENTIFICATION:	Site Name: Sarkari Madrasah-e-Awami (Amarat Kotwal Building)		
		Other Names: ---		
	2. LOCATION:	Address: JAI-6/ 73, Baba-e-Urdu (Mission) Road, Parthana Samaj Road		
		Survey No.	Plot No. 6/ 73	Sheet No.
		Coordinates	N-24.51467	E-67.00604
		District/City/ Town	Karachi	
	3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
		Name of Owner (s)	GOVERNMENT OF SINDH	
4 OCCUPANCY	G+1 (Institute)			
5 REASONS FOR PROTECTION	Architectural Value: (Balconies, Cornices/ Moldings, Pilasters, Decorative Parapet, Timber pitched roof and iron grill works)			
6 MEASUREMENT	Height-30' Length-146' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its social, historical and architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	12-03-2018			


JAHANGIR MANSION

	1. IDENTIFICATION:				
	Site Name:		Jahangir Mansion		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-6/ 57, M. A. Jinnah (Bunder) Road, Shivdas Chandumal Road		
	Survey No.		Plot No. 6/ 57	Sheet No.	
	Coordinates		N-24.51444	E-67.00636	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>		Government	
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd & 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Balconies, Pediments, Cornices/ Moldings, Pilasters, Decorative Parapet and iron grill works)			
6	MEASUREMENT	Height-40' Length-84' Breath-47' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	High Degree Threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound. The Building was constructed in 1922.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its historical and architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	12-03-2018			


ROSHAN MANZIL

	1. IDENTIFICATION:				
	Site Name:		Roshan Manzil		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-6/ 45, 55, M. A. Jinnah (Bunder) Road, Shivdas Chandumal Road		
	Survey No.		Plot No. 6/45,55	Sheet No.	
	Coordinates		N-24.85648	E-67.01027	
	District/City/ Town		Karachi		
	3. OWNERSHIP:		Private ✓	Government	
	Name of Owner (s)		UNKNOWN		
4	OCCUPANCY	(Rented) G+2 +1(GF. Commercial, 1st, 2nd & 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Balconies, Cornices/ Moldings, Pilasters, Decorative Parapet and iron grill works)			
6	MEASUREMENT	Height-58' Length-43' Breath-74' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP				
		PHOTOGRAPH(S) 			
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	12-03-2018			


IBRAHIMJEE HAKIMJEE BUILDING

	1. IDENTIFICATION:				
	Site Name:		Ibrahimjee Hakimjee Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-6/ 35, Parathana Samaj Road, Adamjee Budhabhai Road		
	Survey No.		Plot No. 6/ 35	Sheet No.	
	Coordinates		N-24.85721	E-67.00838	
	District/City/ Town		Karachi		
	3. OWNERSHIP:		Private ✓		Government
Name of Owner (s)		UNKNOWN			
4	OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd & 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Balconies, Decorative Parapet, Bossed stone masonry and iron grill works)			
6	MEASUREMENT	Height-44' Length-52' Breath-47' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	12-03-2018			


CAPTAIN & CO. BUILDING

	1. IDENTIFICATION:				
	Site Name:		Captain & Co. Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-7/ 13, Shahrah-e-Altah Hussain (Napier Road)		
	Survey No.		Plot No. 7/ 13	Sheet No.	
	Coordinates		N-24.8475	E-67.00487	
District/City/ Town		Karachi			
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)		TRUST			
4	OCCUPANCY	(Rented) G+2 (Residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Cornices/ Molding, Pilasters, Decorative Parapet, Timber Pitched Roof, Carved Water Spout)			
6	MEASUREMENT	Height-26' Length-54' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	
9	THEREAT(S)	Second degree threat			
10	LOCATION MAP				
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	12-03-2018			

HALAI WAQF PROPERTY

	1. IDENTIFICATION:				
	Site Name:		Halai Waqf Property		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-1/ 57, Shahrah-e-Altah Hussain (Napier Road), Daryalal Street		
	Survey No.		Plot No. 1/ 57	Sheet No.	
	Coordinates		N-24.858559	E-67.00433	
	District/City/ Town		Karachi		
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)		TRUST			
4	OCCUPANCY	(Rented) G+2+1 (GF. Commercial, 1st, 2nd and 3rd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Roundels, Balconies, Cornices/ Moldings, Pilasters, Decorative Parapet)			
6	MEASUREMENT	Height-44' Length-27' Breath-47' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9	THEREAT(S)	Second degree threat (3rd floor new constructed)			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	13-03-2018			


NOORUDDIN NOMAN BUILDING/ SULTAN BUILDING

	1. IDENTIFICATION:			
	Site Name:	Nooruddin Noman Building/ Sultan Building		
	Other Names:	---		
	2. LOCATION:			
	Address:	JAI-1/ 32, Shahrah-e-Altat Hussain (Napier Road), Gul Mohammad Street		
	Survey No.	Plot No. 1/ 32	Sheet No.	
	Coordinates	N-24.85662	E-67.00369	
	District/City/ Town	Karachi		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	UNKNOWN			
4 OCCUPANCY	(Rented) G+1+1 (GF. Commercial, 1st & 2nd floor residential)			
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Roundels, Cornices/ Moldings, Pilasters, Decorative Parapet)			
6 MEASUREMENT	Height-35' Length-48' Breath-46' Approximately			
7 CONSTRUCTION MATERIAL	Stone building			
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9 THEREAT(S)	Second degree threat			
10 LOCATION MAP				
				
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14 DATE	13-03-2018			


UNKNOWN

	1.	IDENTIFICATION:			
		Site Name:	Unknown-000917		
		Other Names:	---		
	2.	LOCATION:			
		Address:	JAI-1/23, Mohammad Shah Street, Near Tapal House		
		Survey No.	Plot No. 1/23	Sheet No.	
		Coordinates	N-24.85727	E-67.00390	
		District/City/ Town	Karachi		
	3.	OWNERSHIP:	Private ✓	Government	
		Name of Owner (s)	UNKNOWN		
4	OCCUPANCY	G+2 (GF. Commercial, 1st & 2nd floor residential)			
5	REASONS FOR PROTECTION	Architectural Value: (Pilasters, Decorative Parapet and iron grill works)			
6	MEASUREMENT	Height-37' Length-17' Approximately			
7	CONSTRUCTION MATERIAL	Stone building			
8	STATUS/PRESENT CONDITION	Dilapidated ✓	Stable	Good Condition	Needs repair
9	THEREAT(S)	High degree threat			
10	LOCATION MAP	PHOTOGRAPH(S)			
					
					
11	COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>			
12	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13	NAME OF INVESTIGATOR	Muhammad Omar Qureshi			
14	DATE	13-03-2018			


TULSI DAS BUILDING

	1. IDENTIFICATION:				
	Site Name:		Tulsi Das Building		
	Other Names:		---		
	2. LOCATION:				
	Address:		JAI-3/ 28, Chand Bibi Road (Princess Street), Najmudin Street		
	Survey No.		Plot No. 3/ 28	Sheet No.	
	Coordinates		N-24.85838	E-67.00683	
	District/City/ Town		Karachi		
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>		Government
	Name of Owner (s)		UNKNOWN		
4 OCCUPANCY	(Rented) G+3 (GF. Commercial, 1st, 2nd and 3rd floor residential)				
5 REASONS FOR PROTECTION	Architectural Value: (Arches, Pilasters, Decorative Parapet,)				
6 MEASUREMENT	Height-43' Length-28' Approximately				
7 CONSTRUCTION MATERIAL	Stone building				
8 STATUS/PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>	
9 THEREAT(S)	High degree threat, Major alteration in front elevation				
10 LOCATION MAP	PHOTOGRAPH(S)				
					
					
11 COMMENTS	<i>British period Historical back ground and architectural features of the building are sound.</i>				
12 RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>				
13 NAME OF INVESTIGATOR	Muhammad Omar Qureshi				
14 DATE	13-03-2018				


YAQOOB KHAMEESA BUILDING

	1. IDENTIFICATION:	DAP-NED/000941		
	Site Name:	Yaqoob Khameesa Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
Address:	JAI-4/10, Ball Lane			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-	E-		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private V	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Residential & Commercial			
5. REASONS FOR PROTECTION:	Architectural Value			
6. MEASUREMENT:	Height- 60'	Length- 50'	Width- 24'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition V	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. Extra addition on top need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


AHMED CHEMICAL BUILDING

	1. IDENTIFICATION:	DAP-NED/000942		
	Site Name:	Ahmed Chemical Building G + 2 + 1		
	Other Names:			
	2. LOCATION:			
Address:	JAI-4/13/A, James Terrace Road, Najmudin Street			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.531'	E-067'00.437'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value:	Balconies		
6. MEASUREMENT:	Height- 50'	Length- 80'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is well maintained.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


MUTALA HOUSE

	1. IDENTIFICATION:	DAP-NED/000943		
	Site Name:	Mutala House G + 2		
	Other Names:			
	2. LOCATION:			
Address:	JAI-4/13B, Bibi Road, (Princess Street), Najmudin Street			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.470'	E-067'00.553'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 60'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THERAT(S):	Encroachments and weather effects			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	<i>The extra additions on top and elsewhere need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


NASEEM BUILDING

	1. IDENTIFICATION:	DAP-NED/000944		
	Site Name:	Naseem Building G + 2 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-4/13C, Bambayoge Road, Chand Bibi Road, (Princess Street)		
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.531'	E-067'00.447'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE			
UNKNOWN				
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value:	Balconies		
6. MEASUREMENT:	Height- 60'	Length- 70'	Width- 48'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Enchraochments			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The extra additions on top and elsewhere including hoardings which have obscured the visual integrity of the building need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


AHMADI BUILDING

	1. IDENTIFICATION:	DAP-NED/000945		
	Site Name:	Ahmadi Building G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-4/13D, Bambayoge Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.524'	E-067'00.455'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pediments, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 60'	Width- 48'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;">  <p style="font-size: small;">Location Map</p> </div> <div style="width: 45%;"> <p>PHOTOGRAPHS:</p> <div style="display: grid; grid-template-columns: 1fr 1fr; gap: 5px;">     </div> </div> </div>			
11. COMMENTS:	<i>Building is well maintained.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


TIJORI BUILDING

	1. IDENTIFICATION:	DAP-NED/000946		
	Site Name:	Tijori Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-4/15/1, Chand Bibi Road, (Princess Street), Najmudin		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24'51.784'	E-067'01.298'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	-			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The building is partially maintained. The extra addition on top and elsewhere including hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


HILALA MANSION/ ZUBAIDA MANSION

	1. IDENTIFICATION:	DAP-NED/000947		
	Site Name:	Hilala Mansion/ Zubaida Mansion G + 3 + 2		
	Other Names:			
	2. LOCATION:			
Address:	JAI-4/15/2, Chand Bibi Road, (Princess Street), Najmudin			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.784'	E-067'01.298'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and elsewhere including hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


RONAQ-E-ISLAMIA SCHOOL

	1. IDENTIFICATION:	DAP-NED/000948						
	Site Name:	Ronaq-e-Islamia School G + 1 + 1						
	Other Names:							
	2. LOCATION:							
	Address:	JAI-5/2, Chand Bibi Road, (Princess Street),						
	Survey No.	Plot No.	Sheet No.					
	Coordinates	N-24'51.784'	E-067'01.298'					
	District/City/ Town/ Village:							
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government					
	Name of Owner (s) TRUST	PRIVATE						
4. OCCUPANCY:	Educational							
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Pilasters, Cornices/ Moldings							
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'					
7. CONSTRUCTION MATERIAL:	Sand stone							
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair				
9. THEREAT(S):	-							
10. LOCATION MAP:	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;">  <p style="text-align: center;">Location Map</p> </div> <div style="width: 45%;"> <p>PHOTOGRAPHS:</p> <table border="1" style="width: 100%; height: 150px;"> <tr> <td style="width: 50%; text-align: center;">  </td> <td style="width: 50%; text-align: center;">  </td> </tr> <tr> <td style="height: 100px;"></td> <td style="height: 100px;"></td> </tr> </table> </div> </div>							
								
11. COMMENTS:	<i>Building is well maintained. The extra additions on top and elsewhere need to be removed.</i>							
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its educational and architectural value.</i>							
13. NAME OF INVESTIGATOR:	Ejaz Elahi							
14. DATE:	05-03-2018							


LAKHANI MANSION

	1. IDENTIFICATION:	DAP-NED/000949		
	Site Name:	Lakhani Mansion G + 2		
	Other Names:			
	2. LOCATION:			
Address:	JAI-5/5/1, 5/2, Chand Bibi Road, (Princess Street),			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.784'	E-067'01.298'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Encroachments and weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The extra additions and alterations need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


MUHAMMADI MANZIL

	1. IDENTIFICATION:		DAP-NED/000951	
	Site Name:		Muhammadi Manzil G + 3 + 1	
	Other Names:			
	2. LOCATION:			
Address:		JAI-5/22/1, off Baba-e-Urdu (Mission) Road		
Survey No.		Plot No.	Sheet No.	
Coordinates		N-24'51.511	E-067'00.550	
District/City/ Town/ Village:				
3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
Name of Owner (s) UNKNOWN		PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 60'	Length- 70'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and elsewhere including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-03-2018			

NAJMA MANZIL

	1. IDENTIFICATION:	DAP-NED/000952		
	Site Name:	Najma Manzil G + 3 + 1		
	Other Names:			
	2. LOCATION:			
Address:	JAI-5/22/2, off Baba-e-Urdu (Mission) Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.512	E-067'00.542		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 60'	Length- 70'	Width 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather Effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and elsewhere including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-03-2018			

KHADIJA MANZIL


	1. IDENTIFICATION:	DAP-NED/000954		
	Site Name:	Khadija Manzil G + 4		
	Other Names:			
	2. LOCATION:			
Address:	JAI-5/22/5, off Baba-e-Urdu (Mission) Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.530	E-067'00.556		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value:	Balconies, Pilasters		
6. MEASUREMENT:	Height- 60'	Length- 80'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments and weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and elsewhere including untidy electric wires, equipment and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-03-2018			

ABDUR RASOOL BUILDING




1. IDENTIFICATION:	DAP-NED/000955		
	Site Name:	Abdur Rasool Building G + 3	
	Other Names:		
2. LOCATION:	Address:		
	JAI-5/22/7, off Baba-e-Urdu (Mission) Road		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24'51.126	E-067'01.130
	District/City/ Town/ Village:		
3. OWNERSHIP:	Private ✓	Government	
	Name of Owner (s) UNKNOWN	PRIVATE	

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet		
6. MEASUREMENT:	Height- 48'	Length- 70'	Width 48'
	7. CONSTRUCTION MATERIAL: Sand stone		
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓ Needs repair
9. THEREAT(S):	Weather effects		




11. COMMENTS:	<i>The building is partially maintained. The extra fittings including untidy electric wires, equipment and hoardings need to be removed.</i>
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>
13. NAME OF INVESTIGATOR:	Ejaz Elahi
14. DATE:	26-03-2018


TALEEMGAH-E-NISWAN

	1. IDENTIFICATION:	DAP-NED/000956		
	Site Name:	Taleemgah-e-Niswan Government Girls Primary G + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-5/23, Chapa Street, Ali Dina Ali Mohammad Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.725'	E-067'01.210'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
	Name of Owner (s) Provincial	GOVERNMENT		
4. OCCUPANCY:	Educational			
5. REASONS FOR PROTECTION:	Architectural Value: Coupled Columns			
6. MEASUREMENT:	Height- 48'	Length- 100'	Width- 80'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Illegal parking			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its educational and architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	20-03-2018			

BOJHWALA BUILDING

	1. IDENTIFICATION:	DAP-NED/000957		
	Site Name:	Bojhwal Building G + 3		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/1, Adamjee Budhabhai Road, Parathana Samaj Road, Water Course Road,		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24°51.429'	E-067°00.512'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 50'	Length- 100'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is well maintained.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	23-02-20108			

MARVI BUILDING

	1. IDENTIFICATION:	DAP-NED/000958		
	Site Name:	Marvi Building G + 3 + 2		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/8, 9, Adamjee Budhabhai Road, Water Course Road,		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.429'	E-067'00.512'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 90'	Length- 90'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Encroachments			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	<i>The building is partially maintained. The extra additions on top including untidy electric wires, equipment and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	22-02-2018			

TAHSEEN MANZIL



1. IDENTIFICATION:	DAP-NED/000959		
	Site Name:	Tahseen Building G + 3 + 1	
	Other Names:		
2. LOCATION:	Address:		
	JAI-6/10,11, Adamjee Budhabhai Road, Water Course Road,		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24'51.429'	E-067'00.512'
	District/City/ Town/ Village:		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE	



4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet, Pilasters		
6. MEASUREMENT:	Height- 90'	Length- 90'	Width- 50'
7. CONSTRUCTION MATERIAL:	Sand stone		
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9. THEREAT(S):	Encroachments		
10. LOCATION MAP:	PHOTOGRAPHS:		
11. COMMENTS:	<i>The building is well maintained. The extra additions on top including untidy electric wires, equipment and hoardings need to be removed.</i>		
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13. NAME OF INVESTIGATOR:	Ejaz Elahi		
14. DATE:	22-02-2018		

SHEIKH CHAMBER




1. IDENTIFICATION:	DAP-NED/000961		
	Site Name:	Sheikh Chamber G + 2 + 1	
	Other Names:		
2. LOCATION:	Address:		
	JAI-6/23, M.A. Jinnah (Bunder) Road, Adamjee Budhabhai Road		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24'51.561'	E-067'00.381'
	District/City/ Town/ Village:		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN	

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters		
6. MEASUREMENT:	Height- 60'	Length- 100'	Width- 50'
7. CONSTRUCTION MATERIAL:	Sand stone		
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9. THEREAT(S):	Encroachment		



11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and fittings elsewhere including untidy electric wires, equipment and hoardings need to be removed.</i>
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>
13. NAME OF INVESTIGATOR:	Ejaz Elahi
14. DATE:	22-02-2018

SAIFE BUILDING

	1. IDENTIFICATION:	DAP-NED/000962		
	Site Name:	Saife Building G + 3		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/25, M.A. Jinnah (Bunder) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.784'	E-067'01.298'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Coupled Columns			
6. MEASUREMENT:	Height- 48'	Length- 60'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The building is partially maintained. The extra fittings and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	22-02-2018			

KANCHWALA BUILDING



1. IDENTIFICATION:	DAP-NED/000963		
	Site Name:	Kanchwala Building G + 3	
	Other Names:		
2. LOCATION:	Address: JAI-6/28, Adamjee Budhahai Road		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24'51.362'	E-067'00.569'
	District/City/ Town/ Village:		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE	

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies		
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 40'
7. CONSTRUCTION MATERIAL:	Sand stone		
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9. THEREAT(S):	Encroachments		
10. LOCATION MAP:			
	PHOTOGRAPHS: 		
11. COMMENTS:	<i>The building is partially maintained. The extra additions and fittings need to be removed.</i>		
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13. NAME OF INVESTIGATOR:	Ejaz Elahi		
14. DATE:	22-02-2018		

SAWANI NAWAZ BUILDING



1. IDENTIFICATION:	DAP-NED/000964		
	Site Name:	Sawani Nawaz Building G + 3 + 2	
	Other Names:		
2. LOCATION:	Address: JAI-6/31, Adamjee Budhahai Road		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24'51.383'	E-067'00.526'
	District/City/ Town/ Village:		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE	

4. OCCUPANCY:	Commercial & Residential		
----------------------	--------------------------	--	--

5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Roundels, Plasters		
-----------------------------------	--	--	--


6. MEASUREMENT:	Height- 60'	Length- 80'	Width- 40'
------------------------	----------------	----------------	---------------

7. CONSTRUCTION MATERIAL:	Sand stone		
----------------------------------	------------	--	--

8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
-------------------------------------	-------------	--------	--	--------------

9. THERAT(S):	Weather effects		
----------------------	-----------------	--	--

10. LOCATION MAP:	PHOTOGRAPHS:		
--------------------------	---------------------	--	--



11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and fittings need to be removed.</i>		
----------------------	--	--	--

12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
----------------------------	---	--	--

13. NAME OF INVESTIGATOR:	Ejaz Elahi		
----------------------------------	------------	--	--

14. DATE:	22-02-2018		
------------------	------------	--	--


CAPT. M.J. KHAN BUILDING




1. IDENTIFICATION:	DAP-NED/000965		
	Site Name:	Capt. M.J. Khan Building G + 3 + 1	
	Other Names:		
2. LOCATION:	Address: JAI-6/33, Adamjee Budhahai Road		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24'51.409'	E-067'00.519'
	District/City/ Town/ Village:		
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/> Government
Name of Owner (s) UNKNOWN		PRIVATE	

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilaster, Decorative Parapet		
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 48'
7. CONSTRUCTION MATERIAL:	Sand stone		
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9. THEREAT(S):	Weather effects		
10. LOCATION MAP:			
11. COMMENTS:			
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere need to be removed.</i>		
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13. NAME OF INVESTIGATOR:	Ejaz Elahi		
14. DATE:	22-02-2018		


NOOR MANZIL

	1. IDENTIFICATION:	DAP-NED/000966		
	Site Name:	Noor Manzil G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/34/1, Adamjee Budhahai Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.415'	E-067'00.509'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilaster, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 24'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	22-02-2018			


SHEDAI MANZIL

	1. IDENTIFICATION:	DAP-NED/000968		
	Site Name:	Shedai Manzil G + 3 + 2		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/36/2, Parathana Samaj Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.441'	E-067'00.513'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters			
6. MEASUREMENT:	Height- 60'	Length- 60'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere including untidy electric wires and equipment need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	23-02-2018			


BULKA MANSION

	1. IDENTIFICATION:	DAP-NED/000969		
	Site Name:	Bulka Mansion G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/36/3, Parathana Samaj Road		
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.401'	E-067'00.515'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters			
6. MEASUREMENT:	Height- 50'	Length- 60'	Width- 24'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
				
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere including untidy electric wires and equipment need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	23-02-2018			


SUBHASH BUILDING

	1. IDENTIFICATION:	DAP-NED/000970		
	Site Name:	Subhash Building G + 2 + 2		
	Other Names:			
	2. LOCATION:			
Address:	JAI-6/36/3, Parathana Samaj Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.454'	E-067'00.532'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies			
6. MEASUREMENT:	Height- 60'	Length- 60'	Width- 36'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere including untidy electric wires and equipment need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			


KESHOW NIVAS BUILDING

	1.	IDENTIFICATION:	DAP-NED/000971		
		Site Name:	Keshow Nivas Building G + 2 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	JAI-6/42/1, off Parathana Samaj Road		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.318'	E-067'00.575'	
		District/City/ Town/ Village:			
	3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s) UNKNOWN	PRIVATE		
4.	OCCUPANCY:	Commercial & Residential			
5.	REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6.	MEASUREMENT:	Height- 60'	Length- 60'	Width- 60'	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair	
9.	THEREAT(S):	Weather effects			
10.	LOCATION MAP:	PHOTOGRAPHS:			
	 <p style="text-align: center;">Location Map</p>				
11.	COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere including untidy electric wires and equipment need to be removed.</i>			
12.	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	26-02-2018			


REHMAN BUILDING

	1. IDENTIFICATION:	DAP-NED/000972		
	Site Name:	Rehman Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/44/2/1, off M.A. Jinnah (Bunder) Road		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24°51.397'		E-067°00.564'	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters,			
6. MEASUREMENT:	Height- 36'	Length- 60'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: left;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The extra additions on top and fittings elsewhere including untidy electric wires and equipment need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			

MANOHAR MANSION

	1. IDENTIFICATION:	DAP-NED/000973		
	Site Name:	Manohar Mansion G + 2		
	Other Names:			
	2. LOCATION:			
Address:	JAI-6/44/2/2, off M.A. Jinnah (Bunder) Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.395'	E-067'00.568'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 36'	Length- 60'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The extra fittings elsewhere including untidy electric wires and equipment need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			


AFTAB MANSION

	1. IDENTIFICATION:	DAP-NED/000974		
	Site Name:	Aftab Mansion G + 1 + 1		
	Other Names:			
	2. LOCATION:			
Address:	JAI-6/44/2/3, off M.A. Jinnah (Bunder) Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.478'	E-067'00.516'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet Roundels Cornices/ Molding Festoon			
6. MEASUREMENT:	Height- 36'	Length- 50'	Width- 36'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			

PREMJI SHAMA BUILDING

	1. IDENTIFICATION:	DAP-NED/000975		
	Site Name:	Premji Shama Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
Address:	JAI-6/44/3, off M.A. Jinnah (Bunder) Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.400'	E-067'00.570'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Residential & Commercial			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Courtyard			
6. MEASUREMENT:	Height- 48'	Length- 60'	Width- 48'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			

PYARE LAL BUILDING (SURAYA)

	1. IDENTIFICATION:	DAP-NED/000976		
	Site Name:	Pyare Lal Building (Suraya) G + 3		
	Other Names:			
	2. LOCATION:			
Address:	JAI-6/45/2/1, 45/2/2, 45/2/3, off M.A. Jinnah (Bunder) Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.784'	E-067'01.298'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			


BARKAT ALI BUILDING




1. IDENTIFICATION:	DAP-NED/000977		
	Site Name:	Barkat Ali Building G + 3 + 1	
	Other Names:		
2. LOCATION:	Address: JAI-6/45/3, off M.A. Jinnah (Bunder) Road, Shivandas Chandumal Road		
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24°51.419'	E-067°00.554'
	District/City/ Town/ Village:		
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE	

4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Colonnaded/ Arcaded Verandah			
6. MEASUREMENT:	Height- 60'	Length- 65'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9. THEREAT(S):	-			
10. LOCATION MAP:				
10. PHOTOGRAPHS:				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			

AHTESHAM/ M. LAIQ MANSION

	1. IDENTIFICATION:	DAP-NED/000979		
	Site Name:	Ahtesham / M. Laiq Mansion G + 3		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/47 ,54, Shivandas Chandumal Road		
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.398'	E-067'00.575'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Pilaster, Decorative Parapet			
6. MEASUREMENT:	Height- 70'	Length- 100'	Width- 70'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	27-02-2018			

UNKNOWN

	1. IDENTIFICATION:	DAP-NED/000980		
	Site Name:	----- G + 3		
	Other Names:			
	2. LOCATION:			
Address:	JAI-6/50, 51, Shivandas Chandumal Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.416'	E-067'00.600'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Pilaster, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 48'	Width- 24'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	27-02-2018			


HAMALDAS MANUMAL BUILDING



1. IDENTIFICATION:	DAP-NED/000981	
	Site Name:	Hamaldas Manumal Building G + 3
	Other Names:	
2. LOCATION:	Address: JAI-6/58/1, Shivandas Chandumal Road	
	Survey No.	Plot No. Sheet No.
	Coordinates	N-24'51.436' E-067'00.576'
	District/City/ Town/ Village:	
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s) UNKNOWN	PRIVATE

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Pilaster, Decorative Parapet, Pediments		
6. MEASUREMENT:	Height- 60'	Length- 70'	Width- 40'
7. CONSTRUCTION MATERIAL:	Sand stone		
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9. THERAT(S):	Weather effects		
10. LOCATION MAP:			
11. COMMENTS:	PHOTOGRAPHS:		
12. RECOMMENDATIONS	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i> <i>The building deserves to be declared as protected heritage due to its architectural value.</i>		
13. NAME OF INVESTIGATOR:	Ejaz Elahi		
14. DATE:	27-02-2018		

SHAKUR BHAJI BUILDING

	1. IDENTIFICATION: DAP-NED/000982
	Site Name: Shakur Bhai Building G + 2 + 1
	Other Names:
	2. LOCATION: Address: JAI-6/58/2, Shivandas Chandumal Road Survey No. Plot No. Sheet No. Coordinates N-24'51.413' E-067'00.590' District/City/ Town/ Village:
3. OWNERSHIP: Private <input checked="" type="checkbox"/> Government	
Name of Owner (s) UNKNOWN	PRIVATE
4. OCCUPANCY:	Commercial & Residential
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Bossed Stone Masonry, Pilaster, Decorative Parapet, Pediments
6. MEASUREMENT:	Height- 50' Length- 80' Width- 50'
7. CONSTRUCTION MATERIAL:	Sand stone
8 STATUS / PRESENT CONDITION	Dilapidated Stable Good Condition <input checked="" type="checkbox"/> Needs repair
9. THEREAT(S):	Weather effects
10. LOCATION MAP:	PHOTOGRAPHS:
	
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>
13. NAME OF INVESTIGATOR:	Ejaz Elahi
14. DATE:	27-02-2018

MUSTUJAB MANSION


	1. IDENTIFICATION:	DAP-NED/000983		
	Site Name:	Mustujab Mansion G + 2 + 2		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/60, Shivandas Chandumal Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.411'	E-067'00.586'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Pilaster, Colonnaded / Arched Verandah			
6. MEASUREMENT:	Height- 60'	Length- 80'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	-			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	27-02-2018			

HILAL MANZIL




1. IDENTIFICATION:	DAP-NED/000984	
	Site Name:	Hilal Manzil G + 2
	Other Names:	
2. LOCATION:	Address: JAI-6/63/1, Shivandas Chandumal Road	
	Survey No.	Plot No. Sheet No.
	Coordinates	N-24'51.428' E-067'00.576'
	District/City/ Town/ Village:	
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s) UNKNOWN	PRIVATE

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilaster, Colonnaded / Arched Verandah		
6. MEASUREMENT:	Height- 36'	Length- 50'	Width- 40'
7. CONSTRUCTION MATERIAL:	Sand stone		
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9. THERAT(S):	Weather effects		




11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>
13. NAME OF INVESTIGATOR:	Ejaz Elahi
14. DATE:	27-02-2018

GOVIND RAM KATUMAL BUILDING

	1. IDENTIFICATION:	DAP-NED/000985		
	Site Name:	Govind Ram Katumal Building G + 3		
	Other Names:	Khwaja Manzil		
	2. LOCATION:			
Address:	JAI-6/64/1, Shivandas Chandumal Road			
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.438'	E-067'00.578'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 50'	Length- 70'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	<div style="display: flex; align-items: flex-start;"> <div style="flex: 1;">  <p style="font-size: small;">Location Map</p> </div> <div style="flex: 1; padding-left: 10px;"> <p>PHOTOGRAPHS:</p> <div style="display: flex; justify-content: space-around;">   </div> </div> </div>			
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	27-02-2018			

MOHAMMAD ALI BUILDING

	1. IDENTIFICATION:	DAP-NED/000986		
	Site Name:	Mohammad Ali Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/64/2, Shivandas Chandumal Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24°51.435'	E-067°00.580'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 60'	Length- 60'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	27-02-2018			


JAMEEL MANSION



1. IDENTIFICATION:	DAP-NED/000987	
	Site Name:	Jameel Mansion G + 2
	Other Names:	
2. LOCATION:	Address: JAI-6/65/1, Shivandas Chandumal Road	
	Survey No.	Plot No. Sheet No.
	Coordinates	N-24°51.354' E-067°0.629'
	District/City/ Town/ Village:	
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s) UNKNOWN	PRIVATE

4. OCCUPANCY:	Commercial & Residential		
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet, Roundels, Pediments		
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 40'
7. CONSTRUCTION MATERIAL:	Sand stone		
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair

9. THEREAT(S): Weather effects




11. COMMENTS: *Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.*

12. RECOMMENDATIONS *The building deserves to be declared as protected heritage due to its architectural value.*


13. NAME OF INVESTIGATOR: Ejaz Elahi

14. DATE: 28-02-2018


MADHOJEE PREMJEE BUILDING

	1. IDENTIFICATION:	DAP-NED/000988		
	Site Name:	Madhojee Premjee Building G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/65/2, Shivandas Chandumal Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.455'	E-067'00.562'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet, Roundels, Pediments			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;">  </div> <div style="width: 50%;"> <p>PHOTOGRAPHS:</p>  </div> </div>			
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	28-02-2018			


KANWARJEE DAM BUILDING

	1. IDENTIFICATION:	DAP-NED/000989		
	Site Name:	Kanwarjee Dam Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/66/1, Shivandas Chandumal Road		
Survey No.	Plot No.	Sheet No.		
Coordinates	N-24'51.457'	E-067'00.552'		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 30'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	28-02-2018			


BHATIA BHUWANI BUILDING / NAVEED MANZIL

	1. IDENTIFICATION:	DAP-NED/000990		
	Site Name:	Bhatia Bhuwani Building / Naveed Manzil G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/66/2, Shivandas Chandumal Road, Parathana Samaj Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.470'	E-067'00.550'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Coupled Colum			
6. MEASUREMENT:	Height- 60'	Length- 60'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments & weather effects			
10. LOCATION MAP:	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;">  <p style="font-size: small;">Location Map</p> </div> <div style="width: 50%;"> <p>PHOTOGRAPHS:</p>  </div> </div>			
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-02-2018			



KARISHNA NAWAZ BUILDING

	1. IDENTIFICATION:	DAP-NED/000991		
	Site Name:	Karishna Nawaz Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/66/1, Shivandas Chandumal Road, Parathana Samaj Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.447'	E-067'00.561'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies			
6. MEASUREMENT:	Height- 60'	Length- 70'	Width- 70'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	28-02-2018			


SKHAMOOLAL KALYANJEE BUILDING

	1. IDENTIFICATION:	DAP-NED/000992		
	Site Name:	Skhamoolal Kalyanjee Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/69/1, Shivandas Chandumal Road, Parathana Samaj Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.447'	E-067'00.552'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private ✓	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 48'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	28-02-2018			


UNKNOWN

	1. IDENTIFICATION:	DAP-NED/000995		
	Site Name:	----- G + 1 + 1		
	Other Names:			
	2. LOCATION:	Address: JAI-7/1, Shahrah-e-Altah Hussain (Napier Road), Daryalal Street		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.314'		E-067'00.262'
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>		Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Cornices/Molding, Bossed Stone Masonry			
6. MEASUREMENT:	Height- 36'	Length- 80'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	20-03-2018			


FAYZ-E-HUSSAINI MAHAL

	1.	IDENTIFICATION:	DAP-NED/000996		
		Site Name:	Fayz-e-Hussaini Mahal G + 2		
		Other Names:			
	2.	LOCATION:			
		Address:	JAI-7/8,9, Shahrah-e-Altat Hussain (Napier Road)		
		Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.325'		E-067'00.267'	
	District/City/ Town/ Village:				
3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
	Name of Owner (s)	PRIVATE UNKNOWN			
4.	OCCUPANCY:	Commercial & Residential			
5.	REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies			
6.	MEASUREMENT:	Height- 48'	Length- 100'	Width- 80'	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9.	THEREAT(S):	Weather effects			
10.	LOCATION MAP:	PHOTOGRAPHS:			
	 <p>Location Map</p>				
11.	COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12.	RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	20-03-2018			



REHMAN BUILDING (ZEENETH)

	1. IDENTIFICATION:	DAP-NED/000997		
	Site Name:	Rehman Building (Zeeneth) G + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-7/19, M.A. Jinnah (Bunder) Road		
Survey No.	Plot No.	Sheet No.		
Coordinates	N-	E-		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Commercial			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Timber Pitched Roof, colonnaded, Arched Verandah			
6. MEASUREMENT:	Height- 30'	Length- 60'	Width- 35'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	20-03-2018			


ABDULHUSEN KARIMJEE MARVI WAQF BUILDING

	1. IDENTIFICATION:	DAP-NED/000999		
	Site Name:	Abdulhusen Karimjee Marvi Waqf Building G + 4		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-8/8, Chand Bihi Road (Princess Street) Chapa Street		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.434'	E-067'00.351'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 60'	Length- 80'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	20-03-2018			


SABIRA MANZIL

	1. IDENTIFICATION:	DAP-NED/001000		
	Site Name:	Sabira Manzil G + 1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-8/10, Chand Bihi Road (Princess Street) Chapa Street		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.448'	E-067'00.408'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private ✓	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches			
6. MEASUREMENT:	Height- 24'	Length- 80'	Width- 36'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained and required extensive repair works.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	20-03-2018			


FAMILY PARK (NANAKWARA GARDEN)

	1. IDENTIFICATION:	DAP-NED/001001		
	Site Name:	Family Park		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-3/19, Jama Street, Bambayoge Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24°51.784'	E-067°01.298'	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>		
Name of Owner (s) FEDERAL GOVERNMENT	GOVERNMENT			
4. OCCUPANCY:	Public Park			
5. REASONS FOR PROTECTION:	Architectural Value: Lights/ Poles {Pavements/ Walkways, Shutter Trees, Benches, Walls & Fences, Gazebo Umbrellas, Kids Play Land			
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	-			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="font-size: small;">Location Map</p>				
11. COMMENTS:	<i>The Park was constructed in 2006 and well maintained.</i>			
12. RECOMMENDATIONS	<i>The park deserves to be declared as protected heritage due to its recreational and architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	20.3.2018			


BAILA RAM BUILDING

	1. IDENTIFICATION:	DAP-NED/000950		
	Site Name:	Baila Ram Building G + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-5/19, Parathana Samaj Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.784'		E-067'01.298'
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Bossed Stone Masonry, Cornices/ Moldings			
6. MEASUREMENT:	Height- 90'	Length- 120'	Width- 90'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>Building is partially maintained. The roof of the building seems to be reconstructed.</i>			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	05-03-2018			


FAKHARI MANZIL

	1. IDENTIFICATION:	DAP-NED/000953		
	Site Name:	Fakhari Manzil G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-5/22/3, off Baba-e-Urdu (Mission) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.512	E-067'00.551	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Roundels			
6. MEASUREMENT:	Height- 60'	Length- 70'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p style="text-align: center;">Location Map</p>				
11. COMMENTS:	<i>The building is partially maintained. The extra additions on top and elsewhere including untidy electric wires need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-03-2018			


G. MARVI BUILDING

	1. IDENTIFICATION:		DAP-NED/000960		
	Site Name:		G. Marvi Building G + 3		
	Other Names:				
	2. LOCATION:				
	Address:		JAI-6/20, M.A. Jinnah (Bunder) Road		
	Survey No.		Plot No.	Sheet No.	
	Coordinates		N-24'51.344'	E-067'00.551'	
	District/City/ Town/ Village:				
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)		PRIVATE UNKNOWN		
4. OCCUPANCY:	Commercial & Residential				
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet, Pilasters				
6. MEASUREMENT:	Height- 50'	Length- 70'	Width- 50'		
7. CONSTRUCTION MATERIAL:	Sand stone				
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair	
9. THEREAT(S):	-				
10. LOCATION MAP:	PHOTOGRAPHS:				
					
11. COMMENTS:	<i>The building is well maintained. The untidy electric wires, equipment and hoardings need to be removed.</i>				
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>				
13. NAME OF INVESTIGATOR:	Ejaz Elahi				
14. DATE:	22-02-2018				


SHANTI SADAN

	1. IDENTIFICATION:	DAP-NED/000993		
	Site Name:	Shanti Sadan G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	JAI-6/69/2, Shivandas Chandumal Road, Parathana Samaj Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.499'	E-067'00.558'	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private ✓	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Pilasters, Decorative Parapet, Cornices/ Molding			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 48'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Weather effects			
10. LOCATION MAP:	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;">  <p style="font-size: small;">Location Map</p> </div> <div style="width: 50%;"> <p>PHOTOGRAPHS:</p>  </div> </div>			
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires and hoardings need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	28-02-2018			

BANDO MANDIL BUILDING

	1. IDENTIFICATION: Site Name:	DAP-NED/000967 Bando Mandil Building G + 3 + 1		
	Other Names:			
	2. LOCATION: Address:	JAI-6/36/1, Parathana Samaj Road		
	Survey No. Coordinates District/City/ Town/ Village:	Plot No. N-24'51.446'	Sheet No. E-067'00.514'	
3. OWNERSHIP: Name of Owner (s) UNKNOWN	Private <input checked="" type="checkbox"/>	Government		
4. OCCUPANCY:	Commercial & Residential			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 28'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THERAT(S):	Weather effects			
10. LOCATION MAP:	PHOTOGRAPHS:			
				
11. COMMENTS:	<i>Building is partially maintained. The extra addition on top and fittings elsewhere need to be removed.</i>			
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	23-02-2018			

UNKNOWN

	1. IDENTIFICATION:	DAP-NED/000998						
	Site Name:	---- G + 3						
	Other Names:							
	2. LOCATION:							
	Address:	JAI-7/32, off Daryalal Street						
	Survey No.	Plot No.	Sheet No.					
	Coordinates	N-24'51.326'	E-067'00.225'					
	District/City/ Town/ Village:							
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government					
	Name of Owner (s) UNKNOWN	PRIVATE						
4. OCCUPANCY:	Commercial & Residential							
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Bossed Stone Masonry							
6. MEASUREMENT:	Height-	Length-	Width-					
7. CONSTRUCTION MATERIAL:	Sand stone							
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair				
9. THEREAT(S):	Encroachments & weather effects							
10. LOCATION MAP:	<div style="display: flex; align-items: flex-start;"> <div style="width: 30%; text-align: center;">  <p style="font-size: small;">Location Map</p> </div> <div style="width: 70%; padding-left: 10px;"> <p>PHOTOGRAPHS:</p> <table border="1" style="width: 100%; height: 150px;"> <tr> <td style="width: 50%;"></td> <td style="width: 50%;"></td> </tr> <tr> <td style="width: 50%;"></td> <td style="width: 50%;"></td> </tr> </table> </div> </div>							
11. COMMENTS:	<i>Building is partially maintained. The Extra additions and alterations including untidy electric wires need to be removed.</i>							
12. RECOMMENDATIONS	<i>The building deserves to be declared as protected heritage due to its architectural value.</i>							
13. NAME OF INVESTIGATOR:	Ejaz Elahi							
14. DATE:	20-03-2018							